

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22000923/UVF3N2**Date:** 03/03/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001962056
Claimant Vehicle No :	SNA5110L	Insured Vehicle No :	SLT8224X
Date of Loss:	24/01/2022	Nature of Claim:	TP
		Claim No:	268846

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNA5110L		
Make & Model:	BMW 528I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	07157498N52B25AF
Reg. Date:	16/08/2010 (Man. Year: 2010)	Chassis No:	WBAFP32030C545335
Colour:	Black	Odometer:	256882 km
Engine Capacity:	2497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45R18	Rear Tyre Size:	245/45R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,220.63	9,647.68	12,572.95	56.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,340.00	1,520.00	2,820.00	64.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,560.63	11,167.68	15,392.95	57.95
Approved Total (Overridden) (S\$)		8,900.00		
Nett Amount (S\$)	26,560.63	8,900.00	17,660.63	66.49

INSPECTION

Date of Assignment:	26/01/2022	Zoom Auto Werks - Kaki Bukit (HQ) BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE Singapore 417808
Date Inspected:	26/01/2022 Inspected At:	
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Mar 2022)

Parts: 143 BMW 528I 2.0 D/AB 2WD 4DR GAS/D NAV (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SNA5110L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	2,292.00 FL	*- FL
2	2		*FRONT BONNET DAMPERS	Not Necessary	270.00 FL	*- FL
3	2		*FRONT BONNET HINGES	Not Necessary	230.00 FL	*- FL
4	1		*FRONT BONNET LOCK	Not Necessary	210.00 FL	*- FL
5	1		*FRONT BONNET RUBBER	Not Necessary	42.00 FL	*- FL
6	2		*FRONT HEADLAMPS	Holder Cracked	9,241.40 FL	*5,325.80 FL
7	2		*FRONT HEADLAMP LOWER BRACKETS	No such part	226.00 FL	*- FL
8	2		*FRONT GRILLES	Cracked	370.00 FL	*291.40 FL
9	1		*FRONT BUMPER	Dented	1,578.90 FL	*1,455.32 FL
10	2		*FRONT BUMPER BRACKETS	Not Necessary	210.00 FL	*- FL
11	1		*FRONT BUMPER AIR GUIDE	Torn	153.00 FL	*153.00 FL
12	2		*FRONT BUMPER FOG LAMPS	Not Necessary	490.00 FL	*- FL
13	1		*FRONT BUMPER INNER FOAM	Torn	128.00 FL	*128.00 FL
14	1		*FRONT BUMPER CENTRE LOWER GRILLE	Torn	68.00 FL	*68.00 FL
15	2		*FRONT BUMPER SIDE GRILLES	Grazed	108.00 FL	*108.00 FL
16	2		*FRONT BUMPER SIDE GRILLE MOULDINGS	Not Necessary	64.00 FL	*- FL
17	1		*FRONT BUMPER LOGO	Missing	59.00 FL	*59.00 FL
18	1		*FRONT BUMPER LOWER BEAM	Not Necessary	145.00 FL	*- FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	719.00 FL	*611.00 FL
20	2		*FRONT BUMPER REINFORCEMENT STAYS	Twisted	300.00 FL	*- FL
21	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	258.00 FL	*- FL
22	1		*FRONT BUMPER TOP RUBBER SEALS	Necessary	90.00 FL	*90.00 FL
23	1		*FRONT BUMPER TOW HOOK COVER	Not Necessary	40.00 FL	*- FL
24	2		*FRONT BUMPER NOZZLE COVERS	Not Necessary	136.00 FL	*- FL
25	2		*FRONT BUMPER NOZZLE MOTOR ASSY	Not Necessary	390.00 FL	*- FL
26	1		*FRONT BUMPER PDC SENSORS (4 Pcs)	Shorted (1 Pc only)	1,260.00 FL	*185.00 FL
27	1		*FRONT SUPPORT PANEL	Bent	850.00 FL	*541.20 FL
28	1		*FRONT SUPPORT PANEL TOP GARNISH	Cracked	100.00 FL	*100.00 FL
29	2		*FRONT SUPPORT PANEL SIDE GARNISHES	Not Necessary	240.00 FL	*- FL
30	1		*FRONT SUPPORT PANEL STAY	Not Necessary	115.00 FL	*- FL
31	1		*AIR CON CONDENSER	Bent/Punctured	1,185.00 FL	*945.00 FL
32	1		*RADIATOR	Serviceable	1,685.00 FL	*- FL
33	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*50.00 FS
34	1		*FRONT NUMBER PLATE WITH HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	23,383.30	10,150.72
- List Item Discount on L Items 5.00/5.00% (S\$)	1,162.67	503.04
Total Parts (S\$)	22,220.63	9,647.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING	New	80.00	20.00
2	TO REMOVE AND REFIT FRONT SENSOR	New	180.00	50.00
3	TO REMOVE,REPLACE AIR-CON CONDENSER,REFILL GAS & CONDUCT LEAKAGE TEST	New	180.00	100.00
4	TO APPLY UNDERCOATING	New	200.00	0.00
5	PANEL BEATING	New	1,800.00	800.00
6	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,600.00	550.00
7	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	New	300.00	0.00
Gross Labour Cost (\$)			4,340.00	1,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >