5/25/22, 2:48 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000924/KTY3N2

25/05/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00023072200

Claimant Vehicle

SLK5432D

Insured Vehicle No:

SJN3431C

No:

Nature of

Date of Loss:

Reg. Date:

20/01/2022

TP Claim:

Claim SNM22D200620/C02/THAMYL

1ZRY339332

101473 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLK5432D Reg No:

Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A)

20/01/2017 (Man. Year: 2016)

Odometer:

Engine No:

Chassis No:

MR053REH104560101

Colour: Metallic Silver

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 215/45R17 Rear Tyre Size: 215/45R17 Front Left Side: Toyo 5 mm Rear Left Side: Tovo 6 mm Front Right Side: Toyo 5 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,016.25	3,239.67	5,776.58	64.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	720.00	880.00	55.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,616.25	3,959.67	6,656.58	62.70
+ GST 7.00/7.00% (S\$)	743.14	277.18	465.96	62.70
Nett Amount (S\$)	11,359.39	4,236.85	7,122.54	62.70

INSPECTION

Date of Assignment: 28/01/2022

Ah Lim Motor Company (AMK)

10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Date Inspected: 28/01/2022 Inspected At:

Autopoint

Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: **KENNETH KONG** Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

5/25/22, 2:48 PM Adjuster Report

Different 1 cents -Finalise confirm amount: \$3,959.68

5/25/22, 2:48 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 May 2022)

Parts: 143 TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLK5432D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	135.00 FL	*- FL
2	1		*HEADLAMP LH & RH	N/s Mtg Cracked	5,999.60 FL	*2,999.80 FL
3	2		*HEADLAMP CHROME MLDG LH & RH	Serviceable	289.20 FL	*- FL
4	1		*RADIATOR GRILLE BASE ASSY	Cracked	643.00 FL	*643.00 FL
5	1		*RADIATOR GRILLE TOP COVER	Serviceable	80.70 FL	*- FL
6	6		*RADIATOR GRILLE TOP COVER CLIPS	Not Necessary	27.00 FL	*- FL
7	1		*FRONT BUMPER	Buckled	531.10 FL	*531.10 FL
8	1		*FRONT BUMPER LOWER GRILLE	Serviceable	170.10 FL	*- FL
9	1		*FRONT BUMPER SIDE RETAINER LH & RH	N/s Distorted	171.00 FL	*85.50 FL
10	3		*FRONT BUMPER CLIPS	Necessary	13.50 FL	*13.50 FL
11	1		*FRONT BUMPER SPONGE	Serviceable	90.10 FL	*-FL
12	1		*FRONT BUMPER REINFORCEMENT	Repair	399.50 FL	*- FL
13	1		*FRONT FENDER DUAL VVT-I LOGO	Not Necessary	47.60 FL	*- FL
14	1		*FRONT FENDER COWLING LH	Serviceable	227.00 FL	*- FL
15	8		*FRONT FENDER COWLING CLIPS	Not Necessary	23.20 FL	*-FL
16	1		*BRACE PANEL	Repair	149.40 FL	*- FL
17	1		*AIR CON CONDENSER	Serviceable	1,801.70 FL	*- FL
18	1		*RADIATOR SUPPORT PANEL ASSY	Repair	1,136.30 FL	*- FL
19	1		*NUMBER PLATE	Dented	35.00 FS	*35.00 FS
20	1		*RADIATOR COOLANT	Not Necessary	30.00 FS	*- FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	-		
				Sub Total (S\$)	12,000.00	4,307.90
			- List Item Discount on L It	tems 25.00/25.00% (S\$)	2,983.75	1,068.23
				Total Parts (S\$)	9,016.25	3,239.67

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00	20.00
2	TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	100.00	0.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS.	New	60.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT BONNET, FRONT FENDER LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	700.00	300.00
5	TO SPRAY FRONT BONNET, FRONT BUMPER, FRONT FENDER LH.	New	700.00	400.00
	Gross Labou	r Cost (S\$)	1,600.00	720.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >