

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/GRB22000925/KQF3N2**Date:** 03/03/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01

Claimant Vehicle No : SKX5835T **Insured Vehicle No :** SLK5203Z

Date of Loss: 08/01/2022 Nature of Claim: TP Claim No: MFL2022D0000218

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKX5835T**
 Make & Model: TOYOTA AXIO, 1.5 (A) Engine No: 2NR8494686
 Reg. Date: 18/12/2015 (Man. Year: 2015) Chassis No: NRE1610009267
 Colour: Metallic Pearl White Odometer: 65276 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60R15 Rear Tyre Size: 185/60R15
 Front Left Side: Continental 7 mm Rear Left Side: Continental 3 mm
 Front Right Side: Continental 7 mm Rear Right Side: Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,847.62	2,911.11	936.51	24.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,380.00	1,110.00	1,270.00	53.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,227.62	4,021.11	2,206.51	35.43
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	6,227.62	3,200.00	3,027.62	48.62

INSPECTION

Date of Assignment: 26/01/2022

Date Inspected: 27/01/2022 Inspected At:

Kien Cheong Automotive (HQ)
BLK 9 SIN MING INDUSTRIAL ESTATE #01-26
Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2022)
Parts:	143	TOYOTA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKX5835T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	515.60 FL	*515.60 FL
2	1		*FRONT BUMPER RETAINER	Necessary	177.10 FL	*177.10 FL
3	1		*FRONT RH HEAD LAMP	Mtg Cracked	582.30 FL	*582.30 FL
4	1		*FRONT RH FENDER	Bent	731.35 FL	*676.00 FL
5	1		*FRONT RH FENDER INNER SHIELD	Serviceable	371.25 FL	*- FL
6	1		*FRONT RH KUNKLE	Bent	561.60 FL	*497.90 FL
7	1		*FRONT RH LOWER ARM	Distorted	371.25 FL	*371.25 FL
8	1		*FRONT RH WHEEL BEARING	Necessary	230.10 FL	*230.10 FL
9	1		*FRONT RH SHOCK ABSORBER	Bent	571.45 FL	*417.90 FL
10	1		*FRONT RH SHOCK ABSORBER MOUNTING	Serviceable	271.50 FL	*- FL
11	1		*FRONT BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
12	1		*FRONT HEAD LAMP CLIP	Not Necessary	20.00 FS	*- FS
13	1		*FRONT RH FENDER CLIP	Not Necessary	20.00 FS	*- FS
14	1		*FRONT RH FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
15	1		*FRONT RH TYRE RIM	Dented	280.00 FS	*280.00 FS
16	1		*FRONT RH TYRE	Serviceable	180.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,943.50	3,778.15
- List Item Discount on L Items 25.00/25.00% (\$)	1,095.88	867.04
Total Parts (\$)	3,847.62	2,911.11

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WHEEL ALIGNMENT	New	150.00	60.00
2	TO CHECK UP ELECTRICAL WIRING	New	80.00	20.00
3	ANTI RUST	New	100.00	30.00
4	TO REMOVE AND FIX UNDER CARRIAGE	New	450.00	200.00
5	TO RESPRAY PAINTING & ETC	New	600.00	400.00
6	PANEL BEAT,REMOVE AND REPLACING ABOVE PARTS	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,380.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >