

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EQI22000928/GQF3N2**Date:** 23/03/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

Claimant Vehicle No : SJQ2876T**Insured Vehicle No :** SKU53G

Date of Loss: 22/01/2022

Nature of Claim:

TP

Claim No: DM22HO00129

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJQ2876T**

Make & Model: TOYOTA CAMRY, 2.4 L (A)

Engine No: 2AZE134730

Reg. Date: 30/04/2009 (Man. Year: 2009)

Chassis No: MR053BK4007033942

Colour: Beige

Odometer: 209694 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17

Rear Tyre Size:

215/55R17

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,026.90	5,516.50	510.40	8.47
Miscellaneous Items	345.00	270.00	75.00	21.74
Labour	3,600.00	2,550.00	1,050.00	29.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,971.90	8,336.50	1,635.40	16.40
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	9,971.90	6,750.00	3,221.90	32.31
+ GST 7.00/7.00% (S\$)	698.03	472.50	225.53	32.31
Nett Amount (S\$)	10,669.93	7,222.50	3,447.43	32.31

INSPECTION

Date of Assignment: 26/01/2022 Present Location:

SME Motor Pte Ltd (Kaki Bukit)

Date Inspected: 08/02/2022 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 9.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2022)
Parts:	143	TOYOTA CAMRY 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ2876T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT (WCP)	Buckled	380.00 F	*380.00 F
2	2		*REAR BOOT HINGES (WCP)	Bent	130.00 F	*130.00 F
3	1		*REAR BOOT CENTRE LOGO (WCP)	Necessary	40.00 F	*40.00 F
4	1		*REAR BOOT CAMRY PLATE (WCP)	Necessary	35.00 F	*35.00 F
5	1		*REAR BOOT 2.4 PLATE (WCP)	Necessary	35.00 F	*35.00 F
6	1		*REAR BOOT OUTER MOULDING (WCP)	Deformed	175.00 F	*175.00 F
7	1		*REAR BOOT LOCK (WCP)	Bent	150.00 F	*150.00 F
8	1		*REAR BOOT INNER RUBBER (WCP)	Twisted	75.00 F	*75.00 F
9	2		*REAR BOOT LAMP (WCP)	Cracked	300.00 F	*300.00 F
10	1		*REAR BUMPER (WCP)	Deformed	240.00 F	*240.00 F
11	2		*REAR BUMPER RETAINER (WCP)	Not Necessary	70.00 F	*- F
12	10		*REAR BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
13	2		*REAR BUMPER REFLECTOR (WCP)	Cracked	70.00 F	*70.00 F
14	1		*REAR BUMPER REINFORCEMENT (WCP)	Bent	160.00 F	*160.00 F
15	2		*REAR TAIL LAMP (WCP)	Cracked	360.00 F	*360.00 F
16	1		*REAR END PANEL (WCP)	Bent	230.00 F	*230.00 F
17	1		*REAR END PANEL TOP GANRISH (WCP)	Deformed	150.00 F	*150.00 F
18	4		*TOP GARNISH CLIPS (WCP)	Necessary	8.00 F	*8.00 F
19	2		*REAR TAIL LAMP PANEL (WCP)	Buckled	150.00 F	*150.00 F
20	4		*REAR TAIL LAMP CLIPS (WCP)	Necessary	24.00 F	*24.00 F
21	1		*FRT GRILLE (WCP)	Cracked	165.00 F	*165.00 F
22	1		*GRILLE CENTRE LOGO (WCP)	Necessary	40.00 F	*40.00 F
23	4		*GRILLE CLIPS (WCP)	Necessary	8.00 F	*8.00 F
24	1		*FRT BUMPER (WCP)	Deformed	220.00 F	*220.00 F
25	2		*FRT BUMPER RETAINER (WCP)	Not Necessary	64.00 F	*- F
26	10		*FRT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
27	1		*FRT BUMPER REINFORCEMENT (WCP)	Bent	165.00 F	*165.00 F

Report was unsubmitted during this print-out.

3/23/22, 1:01 PM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
28	2		*FRT BUMPER MOULDING (WCP)	Broken	90.00 F	*90.00 F
29	2		*HEADLAMP (WCP)	N/s Cracked/O/s Broken	990.00 F	*990.00 F
30	1		*HEADLAMP SUPPORT PANEL (WCP)	Repair	330.00 F	*- F
31	1		*BRACE PANEL (WCP)	Bent	55.00 F	*55.00 F
32	1		*AIRCON CONDENSER (WCP)	Bent	530.00 F	*530.00 F
F=Franchise part.						
Sub Total (\$\$)					5,479.00	5,015.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					547.90	501.50
Total Parts (\$\$)					6,026.90	5,516.50
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	FRT NUMBER PLATE Bent	35.00	35.00
2	1	RADIATOR COOLANT Not Necessary	25.00	0.00
3	1	REAR NUMBER PLATE Bent	35.00	35.00
4	1	REVERSE SENSOR Damaged	250.00	200.00
Sub Total (\$\$)			345.00	270.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRE CHECKING	New	30.00	30.00
2	REMOVE & REFIX REAR BOOT UPHOLSTERY TO FACILITATE REPAIR	New	120.00	60.00
3	CAVITY PROTECTION ON ALL AFFECTED AREAS	New	150.00	60.00
4	REMOVE & REFIX AIRCON AND GAS	New	100.00	100.00
5	LABOUR CHARGE	New	1,800.00	1,200.00
6	SPRAY PAINTING	New	1,400.00	1,100.00
Gross Labour Cost (\$\$)			3,600.00	2,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >