

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT (SUPPLEMENTARY #1)****Our File No:** CS/EQI22000928/GQF3N2**Date:** 23/03/2022REFERENCE

Handling Insurer: EQ Insurance Company Ltd

Policy No:

**Claimant Vehicle No :** SJQ2876T**Insured Vehicle No :** SKU53G

Date of Loss: 22/01/2022

Nature of Claim:

TP

Claim No: DM22HO00129

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJQ2876T**

Make &amp; Model: TOYOTA CAMRY, 2.4 L (A)

Engine No: 2AZE134730

Reg. Date: 30/04/2009 (Man. Year: 2009)

Chassis No: MR053BK4007033942

Colour: Beige

Odometer: 209694 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	71.50	71.50	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>71.50</b>	<b>71.50</b>	<b>0.00</b>	<b>0.00</b>
<b>+ GST 7.00/7.00% (S\$)</b>	5.01	5.01	0.00	0.00
<b>Nett Amount (S\$)</b>	<b>76.51</b>	<b>76.51</b>	<b>0.00</b>	<b>0.00</b>
<b>+ Previous Recommendations (S\$)</b>		0.00		
<b>Nett Liability (S\$)</b>		<b>76.51</b>		

INSPECTION

Date of Assignment: 21/02/2022 Present Location:

SME Motor Pte Ltd (Kaki Bukit)

Date Inspected: 08/02/2022 Inspected At:

SME Motor Pte Ltd (Kaki Bukit)

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit

Singapore 417883

Estimated Period of Repair: 9.0 days

**Adjuster:** XING GUO QIANG**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2022)
Parts:	143	TOYOTA CAMRY 2.4 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJQ2876T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER INNER SPONGE (WCP)	Cracked	65.00 F	*65.00 F
						F=Franchise part.
					Sub Total (\$\$)	65.00 65.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	6.50 6.50
					Total Parts (\$\$)	71.50 71.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >