

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	ALLIANZ INSURAN	ICE SINGAPORE PTE LTD		Ref:	CS3/AIS22000929/Etf3e2	
	79 ROBINSON RO		Date:	24/02/2022		
				Code:	AIS	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLU 8157B	Veh. Inspected		GBK 9934P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	2022 22003978/SL	Excess (\$)		0.00	
	Assign From	SHANTI	Assign Date		26/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	KDY2318046768	Colour		WHITE	
	Odometer	76557 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	175/75 R15	DUNLOP		4 mm	
	L/H Front Tyre	175/75 R15	DUNLOP		4 mm	
	R/H Rear Tyre	175/75 R15	DUNLOP		4 mm	
	L/H Rear Tyre	175/75 R15	DUNLOP		4 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S POR			Ν.		
5.	5. General Information					
	Accident Date	24/01/2022	Inspect Date / 1	Гime	27/01/2022 (10:05 AM)	
	Survey held at	LOH & LEE MOTOR WORKSHOP				
		BLK 5 PIONEER ROAD NORTH #01-37 SINGAPORE 628458				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORM	ESTIMATED NORMAL PERIOD FOR REPAIR: 10 Working Days				

Report Ref No. CS3/AIS22000929/Etf3e2

Inspected By

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser