

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM22000933/Vty3e2	
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11	I	Date:	11/02/2022	
	ATTN: CHAN KIAN	I CHUAN		Code:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHD 4233C	Veh. Inspected		FBK 2803E	
	Policy No.	VFX/P2419138	Coverage (\$)		0.00	
	Claim No.	S2M03RYP	Excess (\$)		0.00	
	Assign From	CHAN KIAN CHUAN	Assign Date		26/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB400SF	c.c		399	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	NC421603264	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	120/60-70	TIMSUN		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/60-70	TIMSUN		6 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.			IT		
5.	General Information					
	Accident Date	18/01/2022	Inspect Date / T	ime	27/01/2022 (11:00 AM)	
	Survey held at	MOTOPLEX PTE LTD				
	10 KAKI BUKIT ROAD 2 #01-24 FIRST EAST CENTRE SINGAPORE 417868					
5a.	5a. Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500-\$2,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				

Report Ref No. CS3/ASM22000933/Vty3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

Tu

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser