



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 6536R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	UNIT, HEADLAMP (SN)	NOT NECESSARY	2,794.80	-
1	UNIT, HEADLAMP (SN)	BROKEN	2,794.80	2,794.80
1	LAMP ASSY, FOG, LH (SN)	BROKEN	1,009.10	1,009.10
1	COVER ASSY, ENGINE (SN)	NOT NECESSARY	197.00	-
1	GRILLE, RADIATOR (SN)	NOT NECESSARY	180.30	-
1	COVER, FR BUMPER (SN)	BROKEN	547.10	547.10
10	PIECE, RR BUMPER (SN)	NECESSARY	48.00	43.00
1	SUPPORT, FR BUMPER (SN)	NOT NECESSARY	84.70	-
1	SUPPORT, FR BUMPER (SN)	BROKEN	84.70	84.70
2	RETAINER, FR BUMPER (SN)	BROKEN	18.80	18.80
1	SEAL, HOOD TO FR END (SN)	NOT NECESSARY	54.70	-
1	ABSORBER, FR BUMPER (SN)	NOT NECESSARY	140.80	-
1	ABSORBER, FR BUMPER (SN)	NOT NECESSARY	84.20	-
1	REINFORCEMENT, FR (SN)	NOT NECESSARY	260.90	-
1	REINFORCEMENT (SN)	NOT NECESSARY	758.70	-
1	GRILLE SUB-ASSY (SN)	NOT NECESSARY	367.20	-
1	EMBLEM ASSY (SN)	NECESSARY	96.60	96.60
1	FENDER SUB-ASSY, FR (SN)	DENTED	1,037.80	1,037.80
1	LINER, FR FENDER, LH (SN)	TORN	214.50	214.50
1	COVER SUB-ASSY, FR (SN)	MISSING	106.70	106.70
1	MOULDING ASSY (SN)	NOT NECESSARY	633.30	-
1	PANEL SUB-ASSY, FR (SN)	DENTED	1,377.90	1,377.90
1	CHECK ASSY, FR DOOR (SN)	NOT NECESSARY	195.20	-
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	103.10	-
1	HINGE ASSY, FR DOOR (SN)	NOT NECESSARY	117.60	-
1	STRIPE, FR DOOR (SN)	NECESSARY	14.10	14.10
1	STRIPE, FR DOOR (SN)	NECESSARY	46.20	46.20
1	STRIPE, FR DOOR (SN)	NECESSARY	27.90	27.90
1	WHEEL, DISC (SN)	CUT	1,995.20	1,995.20
1	CAP SUB-ASSY, WHEEL (SN)	MISSING	224.20	224.20

Report Ref No. CS/FCI22000935/Eqf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GRAB CONTINENTAL TYRE (SN)	TORN	200.00	88.00
1	JOINT ASSY, LWR BALL (SN)	NOT NECESSARY	278.70	-
1	ARM SUB-ASSY (SN)	NOT NECESSARY	805.40	-
1	ABSORBER SET, SHOCK (SN)	NOT NECESSARY	464.70	-
1	HUB & BEARING ASSY (SN)	NOT NECESSARY	709.60	-
			18,174.50	9,776.60
	LABOUR			
	SUPPLY SEALANT FOR FRONT LH DOOR.		80.00	80.00
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CONDUCT WHEEL ALIGNMENT CHECK.		180.00	180.00
	TO REPLACE FRONT LH TYRE AND SPORT-RIM TO BALANCE TYRE.		100.00	100.00
	TO REPLACE FRONT LH SIDE SUSPENSION.	NOT NECESSARY	720.00	-
	TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP.		180.00	180.00
	TO TRANSFER FRONT LH DOOR GLASS, BOARD, MOTOR, REGULATOR AND OTHER ATTACHMENT TO FACILITATE REPAIRS.		360.00	360.00
	TO REPLACE FRONT LH SIDE ACCIDENT DAMAGE PARTS, STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS.		4,320.00	2,160.00
	TO SPRAY PAINT ON FRONT LH SIDE ACCIDENT AFFECTED AREAS.		3,540.00	2,360.00
			9,660.00	5,600.00
GRAND TOTAL			27,834.50	15,376.60
RECOMMENDED COST OF REPAIRS				15,376.60

Report Ref No. CS/FCI22000935/Eqf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.