

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |  |                                       |                |       |                       |  |
|---|--|---------------------------------------|----------------|-------|-----------------------|--|
|   | MS FIRST CAPITA  | L INSURANCE LTD                       |                | Ref:  | CS/FCI22000935/Eqf3e2 |  |
|   | 36 ROBINSON RO<br>#16-01 CITY HOUS   | AD<br>SESINGAPORE 068877              |                | Date: | 28/03/2022            |  |
|   |  |                                       |                | Code: | FCI2                  |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM  |                                       |                |       |                       |  |
|   | Insured Veh.   | GBH 7111B                             | Veh. Inspected | l     | SLN 6536R             |  |
|   | Policy No.   |                                       | Coverage (\$)  |       | 0.00                  |  |
|   | Claim No.  | D22000283MFCV                         | Excess (\$)    |       | 0.00                  |  |
|   | Assign From  | JOANNE TAN JO ANN                     | Assign Date    |       | 26/01/2022            |  |
| 2.  | 2. Vehicle Particulars & Condition   |                                       |                |       |                       |  |
|   | Make & Model   | TOYOTA PRIUS                          | c.c            |       | 1798                  |  |
|   | Engine No.   | HIDDEN                                | Year of Reg.   |       | 2017                  |  |
|   | Chassis No.  | JTDKB3FU803557977                     | Colour         |       | SILVER                |  |
|   | Odometer   | 275177 KM                             | Steering       |       | IN ORDER              |  |
|   | Brakes   | IN ORDER                              | Modification   |       | SPORTS RIM            |  |
|   | General  | GOOD                                  |                |       |                       |  |
| 3. Conditions of Tyres  |  |                                       |                |       |                       |  |
|   |  | Size                                  | Make           |       | Balance               |  |
|   | R/H Front Tyre   | 195/65 R15                            | BRIDGESTONE    |       | 4 mm                  |  |
|   | L/H Front Tyre   | 195/65 R15                            | BRIDGESTONE    |       | 4 mm                  |  |
|   | R/H Rear Tyre  | 195/65 R15                            | BRIDGESTONE    |       | 4 mm                  |  |
|   | L/H Rear Tyre  | 195/65 R15                            | BRIDGESTONE    |       | 4 mm                  |  |
| 4.  | 4. Description of Damages  |                                       |                |       |                       |  |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  |                                       |                |       |                       |  |
|   | DAMAGES SEE DETAILS.   |                                       |                |       |                       |  |
| 5.  | General Information  |                                       |                |       |                       |  |
|   | Accident Date  | 26/01/2022                            | Inspection Dat | е     | 27/01/2022            |  |
|   | Survey held at   | BORNEO MOTORS (S) PTE LTE             | )              |       |                       |  |
|   |  | 2 PANDAN CRESCENT<br>SINGAPORE 128462 |                |       |                       |  |
| 5a.   | Remarks  |                                       |                |       |                       |  |
|   | A)DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                       |                |       |                       |  |
| 5b.   | Estimate Days of Repair  |                                       |                |       |                       |  |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days   |                                       |                |       |                       |  |
|   |  |                                       |                |       |                       |  |