

TPAXA.
Xiao Chun.

SMW 9476 B. 2020 Dec

Mazda 6 1998cc

JM6GL 1073L0404538

Rear Bumper	Deformed	1266	✓
Rear Bumper Clips.	nr	30(SN)	✓
Rear Bumper Side Holder RH	Crushed	43.40	✓
Rear Bumper Tow Cover	Missing	27.50	✓
Rear Bumper Reflector RH.	Crushed	65.10	✓
Rear Bumper Reinforcement.	NP nr	583.30	X
Rear Bumper Reverse Sensor RH	Deformed	233.50	✓
Rear Bumper Reverse Sensor Cover RH.	nr	15.90	✓
Rear Fender Inner Shield LH.	Torn	108.80	✓
Rear Fender Inner Shield Clips.	nr	20(SN)	✓
Taillamp RH.	Crushed	1592.30	✓

3352.80

2682.20 S-N: 50

SMW 9476B.

Panel Beating

~~500~~ 300

Spray Painting.

~~600~~ 400

Wiring.

~~50~~ 30

To remove reverse sensor.

~~100~~ 50 8/10

To spray tuff coat.

~~150~~ 30

Total: 354.20

L/s : 2.8k

03 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.8k