



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 7590R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	GREY METALLIC 2 REVERSE SENSOR (SN)	BROKEN	158.30	101.05
1	COVER,RR BUMPER (SN)	DENTED	589.50	589.50
1	REINFORCEMENT,RR (SN)	DENTED	423.90	423.90
1	RETAINER,RR BUMPER L (SN)	NOT NECESSARY	116.00	-
1	RETAINER,RR BUMPER R (SN)	NOT NECESSARY	116.00	-
1	LAMP ASSY,RR LH (SN)	BROKEN	374.50	374.50
1	REAR BOOT LID EMBLEM (SN)	NECESSARY	50.70	50.70
1	PLATE,LUGGAGE COMPT (SN)	NECESSARY	43.50	43.50
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	PLATE,LUGGAGE COMPT (SN)	NECESSARY	48.30	48.30
			2,020.70	1,681.45
<b><u>LABOUR</u></b>				
RESET AND REPROGRAMME ECU.			180.00	180.00
DRILL HOLE TO INSTALL REVERSE SENSOR.			180.00	180.00
STRAIGHTEN TAIL-LAMP PANEL.REPLACE AND REALIGN REAR BUMPER.REPAIR REAR BOOT.			2,160.00	1,080.00
SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.			1,770.00	1,180.00
			4,290.00	2,620.00
<b>GRAND TOTAL</b>			<b>6,310.70</b>	<b>4,301.45</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>4,301.45</b>
------------------------------------	--	--	-----------------

Report Ref No. CS/SMR22000941/Evcn2

CHEN TSUE YEE

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.