



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLH 4878Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED	588.00	588.00
1	REAR BUMPER LOWER COVER	CUT	144.00	144.00
1	REAR BUMPER UNDER CENTER COVER	CUT	30.00	30.00
1	REAR BUMPER REFLECTOR RH	CRACKED	32.00	32.00
1	REAR BUMPER REINFORCEMENT	DENTED	435.30	435.30
1	REAR BUMPER REINFORCEMENT BEAM RH	DENTED	142.70	142.70
1	REAR BUMPER RETAINER RH	NECESSARY	39.20	39.20
1	REAR END PANEL	TO REPAIR SEE LABOUR	417.70	-
1	REAR END PANEL GARNISH	CUT	64.00	64.00
1	BOOT LID	TO REPAIR SEE LABOUR	1,490.00	-
1	BOOT LID REFLECTOR RH	SCRATCHED	868.00	868.00
1	BOOT LID "H" EMBLEM	NECESSARY	27.50	27.50
1	BOOT LID "SONATA" EMBLEM	NECESSARY	42.20	42.20
1	BOOT LID HINGE RH	SERVICEABLE	152.80	-
1	BOOT LID RUBBER	SERVICEABLE	99.50	-
1	BOOT LID LOCK	JAMMED	112.00	112.00
1	BOOT LID STRIKER	BENT	22.00	22.00
1	BOOT FLOOR PANEL COVER	SERVICEABLE	216.20	-
1	TAILLAMP RH	SCRATCHED	794.20	794.20
	LESS 20% DISCOUNT		-1,143.46	-668.22
			4,573.84	2,672.88
<u>SPECIAL NETT ITEMS</u>				
1	SET REVERSE SENSORS (SN)	CUT	250.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	20.00
1	SET BOOT LID INNER CLIPS (SN)	NECESSARY	30.00	20.00
			310.00	240.00

Report Ref No. CS/SMR22000944/Vvcn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	LABOUR CHARGES TO PANEL BEATING, REMOVE, RENEW AND ALIGN REPLACED PARTS ETC. INCLUSIVE OF THE REPAIR OF REAR END PANEL AND BOOT LID.		800.00	600.00
	TO JACK AND REPAIR REAR EXHAUST TAIL PIPE.		100.00	50.00
	TO REMOVE AND REFIT BACK-UP CAMERA.		60.00	20.00
	TO REMOVE AND REFIT REVERSE SENSORS.		60.00	20.00
	SPRAY PAINTING.		1,000.00	800.00
	WIRING CHARGES.		50.00	20.00
	TUFF-KOTE.		50.00	20.00
			2,120.00	1,530.00
GRAND TOTAL			7,003.84	4,442.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,550.00

Report Ref No. CS/SMR22000944/Vvcn2

THEVAN THOMAS KARTHIKESAVAN

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.