

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP20120005

Date: 30 DEC 2020

Kathleen C Liem

c/o Hup Ley Huat Motor Spray Painting Services

Blk 1, #01- 35

Kaki Bukit Ave 6

Singapore 417883

THIRD PARTY SURVEY

ACCIDENT OCCURED ON 11 DEC 2020

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services

Blk 1, #01- 35

Kaki Bukit Ave 6

Singapore 417883

As per your instruction dated

16 DEC 2020

with regard to the above matter.

We have carried out a physical inspection on the said

SY234K

We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SY234K

Model : TOYOTA ESTIMA 3.0

Year / Capacity : Sep 2003 / 2998 cc

Chassis No : MCR300062392

Engine No : 1MZ4705784

Mileage : 222 791 km

Colour : Metallic Marron

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR O/S :	215/60/R16	Michelin	9.00 mm	Sport
FRONT N/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR N/S :	215/60/R16	Michelin	9.00 mm	Sport

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SY234K

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front bumper	bent/distorted	\$ 789.50	\$ 789.50
1 pc	Front bumper side retainer	deformed	\$ 42.50	\$ 42.50
1 pc	Front bumper side attachment	distorted	\$ 65.00	\$ 65.00
2 pcs	Front bumper parking sensor cover	deformed	\$ 42.00	\$ 42.00
1 pc	Fog lamp assy	electronically shocked	\$ 250.00	\$ 250.00
1 pc	Headlamp assembly	electronically shocked	\$ 855.00	\$ 855.00
2 pcs	Headlamp clips	necessary	\$ 50.00	\$ 50.00
1 pc	Front support panel	dent/distorted	\$ 974.45	\$ 974.45 XR
1 pc	Front fender	bent	\$ 781.45	\$ 781.45
1 pc	Front fender splash shield	bent	\$ 107.00	\$ 107.00
8 pcs	Front fender splash shield clips	necessary	\$ 40.00	\$ 40.00
1 pc	Front knuckle arm	bent	\$ 381.50	\$ 381.50
1 pc	Front lower arm	bent	\$ 261.55	\$ 261.55
1 pc	Front lower arm ball joint	bent	\$ 92.50	\$ 92.50
1 pc	Front absorber	bent	\$ 425.00	\$ 425.00
1 pc	Front wheel bearing kit	distorted	\$ 85.00	\$ 85.00
1 pc	Front wheel bearing hup	bent	\$ 182.55	\$ 182.55
1 pc	Front wheel housing panel	bent	\$ 591.40	\$ 591.40 XR
1 pc	Reservoir tank	cracked	\$ 156.00	\$ 156.00

	Parts Sub-Total	\$ 6,172.40	\$ 6,172.40
Discount	25.00%	\$ 1,543.10	\$ 1,543.10
		\$ 4,629.30	\$ 4,629.30

4606.55

3454.91

Vehicle Number : SY234K

SPARE PARTS



QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Front bumper parking sensor	electronically shocked	\$ 250.00	\$ 200.00
1 pc	Front wheel rim (sport)	damaged	\$ 600.00	\$ 600.00
1 pc	Front wheel tyre (sport)	damaged	\$ 400.00	\$ 380.00 XNN
				800
Special Nett Sub-Total			\$ 1,250.00	\$ 1,180.00
Spare Parts Total			\$ 5,879.30	\$ 5,809.30



LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 5,879.30	\$ 5,809.30
1	Towing	\$ 120.00	\$ 120.00 80
2	To tuff coat affected areas	\$ 180.00	\$ 150.00 30
3	To remove and refix interior upholstery	\$ 180.00	\$ 150.00 XNN
4	To remove and refix radiator and top up coolant	\$ 180.00	\$ 150.00 XNN
5	To remove and refix air con condenser, piping, vacuum & top up gas	\$ 180.00	\$ 150.00 XNN
6	To check wiring system	\$ 180.00	\$ 150.00 30
7	To remove and replace front undercarriage	\$ 280.00	\$ 250.00 150
8	To check and adjust computer wheel alignment (before and after)	\$ 180.00	\$ 150.00 100
9	To respray affected areas	\$ 1,600.00	\$ 1,400.00 700
10	To renew damaged parts, straighten and repair frt fender inner, front chassis member and aligned all parts	\$ 1,800.00	\$ 1,600.00 700
11	To remove and replace front parking sensor	\$ 180.00	\$ 150.00 30
			1970
	Total	\$ 10,939.30	\$ 10,229.30
			6224.91
	The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :	\$ 8,700.00	LS\$4950
			6 DAYS




Fong Kok Heng
Qualified Appraiser








INSPECTION
SURVEY




OMAX SUR





ARVEY



ARVEY



ARVEY





URVEY





UTOMAX SUR

URVEY




MAX

URVEY




AX
SURVEY



AX
SURVEY

SURVEY



TOMAX