

# AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP20120005

Date: 30 DEC 2020

**Kathleen C Liem**

**c/o Hup Ley Huat Motor Spray Painting Services**

**Blk 1, #01- 35**

**Kaki Bukit Ave 6**

**Singapore 417883**

## THIRD PARTY SURVEY

ACCIDENT OCCURED ON 11 DEC 2020

Workshop Name and Address

Hup Ley Huat Motor Spray Painting Services

Blk 1, #01- 35

Kaki Bukit Ave 6

Singapore 417883

As per your instruction dated

16 DEC 2020

with regard to the above matter.

We have carried out a physical inspection on the said

SY234K

We enclosed herewith our report and findings as follows:

## 1. VEHICLE PARTICULARS

Registration No : SY234K

Engine No : 1MZ4705784

Model : TOYOTA ESTIMA 3.0

Mileage : 222 791 km

Year / Capacity : Sep 2003 / 2998 cc

Colour : Metallic Marron

Chassis No : MCR300062392

## 2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR O/S :	215/60/R16	Michelin	9.00 mm	Sport
FRONT N/S :	215/60/R16	Michelin	9.00 mm	Sport
REAR N/S :	215/60/R16	Michelin	9.00 mm	Sport

## AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

### 3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the **Front** portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete

5. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey done on a **"Without Prejudice"** basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us **within 1 week**, or the report will be treated as correct.

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : SY234K

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>List Items</i>				
1 pc	Front bumper	bent/distorted	\$ 789.50	\$ 789.50
1 pc	Front bumper side retainer	deformed	\$ 42.50	\$ 42.50
1 pc	Front bumper side attachment	distorted	\$ 65.00	\$ 65.00
2 pcs	Front bumper parking sensor cover	deformed	\$ 42.00	\$ 42.00
1 pc	Fog lamp assy	electronically shocked	\$ 250.00	\$ 250.00
1 pc	Headlamp assembly	electronically shocked	\$ 855.00	\$ 855.00
2 pcs	Headlamp clips	necessary	\$ 50.00	\$ 50.00
1 pc	Front support panel	dent/distorted	\$ 974.45	\$ 974.45
1 pc	Front fender	bent	\$ 781.45	\$ 781.45
1 pc	Front fender splash shield	bent	\$ 107.00	\$ 107.00
8 pcs	Front fender splash shield clips	necessary	\$ 40.00	\$ 40.00
1 pc	Front knuckle arm	bent	\$ 381.50	\$ 381.50
1 pc	Front lower arm	bent	\$ 261.55	\$ 261.55
1 pc	Front lower arm ball joint	bent	\$ 92.50	\$ 92.50
1 pc	Front absorber	bent	\$ 425.00	\$ 425.00
1 pc	Front wheel bearing kit	distorted	\$ 85.00	\$ 85.00
1 pc	Front wheel bearing hup	bent	\$ 182.55	\$ 182.55
1 pc	Front wheel housing panel	bent	\$ 591.40	\$ 591.40
1 pc	Reservoir tank	cracked	\$ 156.00	\$ 156.00
Parts Sub-Total			\$ 6,172.40	\$ 6,172.40
Discount 25.00%			\$ 1,543.10	\$ 1,543.10
			\$ 4,629.30	\$ 4,629.30

Vehicle Number : SY234K

**SPARE PARTS**

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<i>Special Nett Items</i>				
1 set	Front bumper parking sensor	electronically shocked	\$ 250.00	\$ 200.00
1 pc	Front wheel rim (sport)	damaged	\$ 600.00	\$ 600.00
1 pc	Front wheel tyre (sport)	damaged	\$ 400.00	\$ 380.00
Special Nett Sub-Total			\$ 1,250.00	\$ 1,180.00
Spare Parts Total			\$ 5,879.30	\$ 5,809.30

### LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 5,879.30	\$ 5,809.30
1	Towing	\$ 120.00	\$ 120.00
2	To tuff coat affected areas	\$ 180.00	\$ 150.00
3	To remove and refix interior upholstery	\$ 180.00	\$ 150.00
4	To remove and refix radiator and top up coolant	\$ 180.00	\$ 150.00
5	To remove and refix air con condenser, piping, vacuum & top up gas	\$ 180.00	\$ 150.00
6	To check wiring system	\$ 180.00	\$ 150.00
7	To remove and replace front undercarriage	\$ 280.00	\$ 250.00
8	To check and adjust computer wheel alignment (before and after)	\$ 180.00	\$ 150.00
9	To respray affected areas	\$ 1,600.00	\$ 1,400.00
10	To renew damaged parts, straighten and repair frt fender inner, front chassis member and aligned all parts	\$ 1,800.00	\$ 1,600.00
11	To remove and replace front parking sensor	\$ 180.00	\$ 150.00
	Total	\$ 10,939.30	\$ 10,229.30

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :




\$ 8,700.00

Fong Kok Heng  
Qualified Appraiser






VEY  
★  
AUTO






ns









INSPECTION  
SURVEY





OMAX SUR















URVEY



UTOMAX SUR



URVEY



MAX



URVEY




AX  
SURVEY



AX  
SURVEY



SURVEY



TOMAX