



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YP 7646K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
2	TAILLAMP @\$412.50 (CONSISTENT)	NOT DAMAGED	825.00	-
	LESS 15% DISCOUNT		-123.75	-
			701.25	-
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR TOWING FORK (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	18,500.00	-
1	REAR TOWING FORK HYDRAULIC INNER (SN) (CONSISTENT)	BENT	8,750.00	7,437.50
1	REAR TOWING FORK HYDRAULIC PIPE (SN) (CONSISTENT)	NECESSARY	650.00	520.00
2	REAR TOWING FORK HYDRAULIC PIN @\$410.00 (SN) (CONSISTENT)	NECESSARY	820.00	656.00
1	REAR TOWING FORK HYDRAULIC UPPER (SN) (CONSISTENT)	NOT DAMAGED	4,820.00	-
1	REAR TOWING FORK HYDRAULIC PIPE (SN) (CONSISTENT)	NOT NECESSARY	650.00	-
1	REAR TOWING FORK HYDRAULIC LOWER (SN) (CONSISTENT)	BENT	4,820.00	4,097.00
1	REAR TOWING FORK HYDRAULIC PIPE (SN) (CONSISTENT)	NOT NECESSARY	650.00	-
2	REAR TOWING FORK HYDRAULIC PIN LOWER @\$410.00 (SN) (CONSISTENT)	NECESSARY	820.00	656.00
1	REAR END PANEL (SN) (CONSISTENT)	TO REPAIR SEE LABOUR	6,800.00	-
1	REAR END PANEL REFLECTOR STICKER (SN) (CONSISTENT)	NECESSARY	650.00	300.00
1	REAR END PANEL STICKER '60KM/H' (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	REAR TOWING FORK HYDRAULIC OIL (SN) (CONSISTENT)	NECESSARY	280.00	180.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
1	REAR REVERSE CAMERA (SN) (CONSISTENT)	NOT NECESSARY	480.00	-
			48,890.00	13,886.50
<b><u>LABOUR</u></b>				
	R&R REAR TOWING FORK .		1,000.00	800.00

Report Ref No. CC4/ASM22000946/Bpa3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	R&R REAR TOWING FORK HYDRAULIC.		1,500.00	1,000.00
	R&R REVERSE CAMERA .	NOT NECESSARY	100.00	-
	CHECK WIRING.	NOT NECESSARY	100.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR TOWING FORK AND REAR END PANEL .		2,800.00	400.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,600.00	200.00
			7,300.00	2,400.00
<b>GRAND TOTAL</b>			<b>56,891.25</b>	<b>16,286.50</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>13,050.00</b>
---	--	--	------------------

Report Ref No. CC4/ASM22000946/Bpa3q2

**LIM TEOW GUAN**

**Automotive Assessor**

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.