

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000950/EVY3M4**Date:** 15/06/2022**REFERENCE**Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00000512204

**Claimant Vehicle No :** SLC9798P**Insured Vehicle No :** SKN7255G

Date of Loss: 17/01/2022

Nature of Claim: TP

Claim No: SNM22D200460/C02/CSC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SLC9798P**

Make &amp; Model: SUBARU FORESTER, 2.0 (A)

Engine No: FA20A930996

Reg. Date: 31/05/2016 (Man. Year: 2016)

Chassis No: JF1SJGK85GG072238

Colour: Silver

Odometer: 102758 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 225/55 R18

Rear Tyre Size: 225/55 R18

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,132.10	2,992.56	1,139.54	27.58
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,735.00	2,555.00	1,180.00	31.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>7,867.10</b>	<b>5,547.56</b>	<b>2,319.54</b>	<b>29.48</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	550.70	388.33	162.37	29.48
<b>Nett Amount (\$\$)</b>	<b>8,417.80</b>	<b>5,935.89</b>	<b>2,481.91</b>	<b>29.48</b>

**INSPECTION**

Date of Assignment: 15/02/2022

Date Inspected: 27/01/2022 Inspected At:

MOTOR IMAGE ENTERPRISES PTE LTD (LENG KEE)  
25 LENG KEE ROAD  
SINGAPORE 159097

Estimated Period of Repair: 4.0 days

**Adjuster:** CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 15 Jun 2022)
Parts:	M1-SUV	SUBARU FORESTER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLC9798P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSEMBLY-HEAD LEFT	Broken	2,380.00 F	*2,380.00 FL
2	1		*COVER ASSEMBLY-LAMP WASHER NOZZLE, LEFT	Not Necessary	55.50 F	*- FL
3	1		*NOZZLE-LAMP WASHER, LEFT	Not Necessary	81.40 F	*- FL
4	1		*BUMPER FACE-FRONT	Dented	610.50 F	*610.50 FL
5	1		*COVER-FRONT BUMPER, LEFT	Not Necessary	13.00 F	*- FL
6	1		*COVER-FOG LIGHT, LEFT	Cut	44.40 F	*44.40 FL
7	1		*BRACKET-FRONT BUMPER SIDE, LEFT	Broken	13.00 F	*13.00 FL
8	1		*BRACKET-FRONT BUMPER CORNER, LEFT	Broken	37.00 F	*37.00 FL
9	1		*ENERGY ABSORBER-FRONT BUMPER	Not Necessary	129.50 F	*- FL
10	1		*FENDER FRONT LEFT	Dented	277.50 F	*277.50 FL
11	1		*BRKT CORNER F LH	Repeated	37.00 F	*- FL
12	1		*CLIP GROMMET	Necessary	3.70 F	*3.70 FL
13	1		*CLIP BMPR	Necessary	24.00 F	*24.00 FL
14	1		*GRILLE ASSY F LWRHG	Broken	325.60 F	*325.60 FL
15	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
					Sub Total (\$\$)	4,132.10 3,735.70
					- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00 743.14
					Total Parts (\$\$)	4,132.10 2,992.56

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REPLACE FRONT BUMPER, ENERGY ABSORBER, LHS FOG LAMP COVER (2 X 560)	New	1,740.00	1,120.00
2	TO RESPRAY FRONT BUMPER(1), ENERGY ABSORBER AND LHS FENDER(1) (440 X 2)	New	1,440.00	880.00
3	TO CONDUCT FRONT LIGHTING TEST	New	150.00	150.00
4	TO REPAIR AND RESPRAY SUPPORT PANEL	New	280.00	280.00
5	TO REMOVE AND REINSTALL HEADLAMP WASHER PIPING	New	125.00	125.00
<b>Gross Labour Cost (\$)</b>			<b>3,735.00</b>	<b>2,555.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >