

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000951/UTY3Q2**Date:** 04/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNA00059142100
Claimant Vehicle No :	SH1904T	Insured Vehicle No :	SLA9317E
Date of Loss:	25/01/2022	Nature of Claim: TP	Claim No: SNM22D200660/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH1904T		
Make & Model:	HYUNDAI ELANTRA, 1.6 ABS D/AB 2WD 4DR (A)	Engine No:	G4FGEU256221
Reg. Date:	22/05/2014 (Man. Year: 2014)	Chassis No:	KMHDH41CMEU129082
Colour:	Yellow/Black	Odometer:	941377 km
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,360.00	2,216.80	1,143.20	34.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,430.00	650.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,440.00	3,646.80	1,793.20	32.96
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	5,440.00	2,900.00	2,540.00	46.69
+ GST 7.00/7.00% (S\$)	380.80	203.00	177.80	46.69
Nett Amount (S\$)	5,820.80	3,103.00	2,717.80	46.69

INSPECTION

Date of Assignment:	27/01/2022		
Date Inspected:	27/01/2022	Inspected At:	Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365
Estimated Period of Repair:	3.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Mar 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 ABS D/AB 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH1904T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S REAR LAMP	Not Necessary	462.00 FL	*- FL
2	1		*N/S REAR LAMP PANEL	Repair	171.00 FL	*- FL
3	3		*N/S REAR LAMP CLIP HOLDER	Not Necessary	22.50 FL	*- FL
4	1		*REAR END PANEL	Badly Dented	385.00 FL	*385.00 FL
5	1		*REAR END PANEL INNER TRIM	Twisted	55.00 FL	*55.00 FL
6	1		*REAR BUMPER	Distorted	385.00 FL	*385.00 FL
7	1		*REAR BUMPER REFLECTOR N/S	Not Necessary	75.00 FL	*- FL
8	1		*REAR BUMPER BRACKET N/S	Bent	41.00 FL	*41.00 FL
9	1		*REAR BUMPER SIDE BRACKET N/S	Cracked	26.00 FL	*26.00 FL
10	1		*REAR BUMPER TOP BRACKET N/S	Cracked	18.00 FL	*18.00 FL
11	1		*REAR BUMPER -LOWER	Deformed	251.00 FL	*251.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Cracked	277.00 FL	*277.00 FL
13	10		*REAR BUMPER CLIPS	Necessary	45.00 FL	*45.00 FL
14	1		*REAR WINDSCREEN MOULDING	Not Necessary	235.00 FL	*- FL
15	1		*BOOTLID	Badly Dented	1,128.00 FL	*1,128.00 FL
16	1		*BOOTLID ELANTRA BADGE	Necessary	49.00 FL	*49.00 FL
17	1		*BOOTLID GLS BADGE	Necessary	26.00 FL	*26.00 FL
18	1		*BOOTLID CENTRE EMBLEM BADGE	Not Necessary	26.00 FL	*- FL
19	1		*BOOTLID RUBBER WEATHERSTRIP	Twisted	85.00 FL	*85.00 FL
20	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,112.50	2,771.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	752.50	554.20
Total Parts (\$\$)	3,360.00	2,216.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	40.00	40.00
2	TO REMOVE AND REIFT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR	New	100.00	60.00
3	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	80.00	60.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	PANEL BEATING KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,000.00	600.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	700.00	600.00
7	TO RUST PROOFING OF THE AFFECTED AREAS	New	100.00	50.00
Gross Labour Cost (\$\$)			2,080.00	1,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >