

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI22000956/KQY3E2

**Date:** 20/05/2022

### REFERENCE

Insured/Claimant: HUSSEIN BIN KAMARUDIN Policy No: DMPCSNW00062352100

Date of Loss: 22/09/2021

Nature of Claim: OD

Claim No: SNM21D206219/C01/TANCHC

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJZ7606B**

Make & Model: HYUNDAI AVANTE, 1.6 (A)

Engine No: G4FCAU860428

Reg. Date: 24/12/2010 (Man. Year: 2010)

Chassis No: KMHU41BMAU033748

Colour: White

Odometer: 0 km

Engine Capacity: 1591 cc

Market Value/New Car Price: S\$28,000.00

Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/45Z R17

Rear Tyre Size:

225/45Z R17

Front Left Side: RADAR 9 mm

Rear Left Side:

RADAR 9 mm

Front Right Side: RADAR 9 mm

Rear Right Side:

RADAR 9 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,452.00	8,160.00	3,292.00	28.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,986.45	2,645.60	340.85	11.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>14,438.45</b>	<b>10,805.60</b>	<b>3,632.85</b>	<b>25.16</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>8,600.00</b>		
<b>- Excess (S\$)</b>	0.00	3,500.00	-3,500.00	
<b>(S\$)</b>	14,438.45	5,100.00	9,338.45	64.68
<b>+ GST 7.00/7.00% (S\$)</b>	1,010.69	357.00	653.69	64.68
<b>Nett Amount (S\$)</b>	<b>15,449.14</b>	<b>5,457.00</b>	<b>9,992.14</b>	<b>64.68</b>

### INSPECTION

Date of Assignment: 27/01/2022

Date Inspected: 27/01/2022 Inspected At:

5035 Ang Mo Kio Industrial Park 2 #01-367

Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 14.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 May 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7606B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Total Parts		10,247.00 F	*6,955.00 F
Supplementary #1						
2	1		*LWR WINDSCREEN COVER	Cracked	165.00 F	*165.00 F
3	1		*INSTRUMENT PNL TRIM	Cracked	210.00 F	*210.00 F
4	1		*AIR INTAKE HOSE	Cracked	60.00 F	*60.00 F
5	1		*AIR INTAKE HOUSING	Cracked	110.00 F	*110.00 F
6	1		*FUSE BOX	Cracked	580.00 F	*580.00 F
7	1		*MODULE BOX HOUSING	Cracked	80.00 F	*80.00 F
F=Franchise part.						
Total Parts (S\$)					11,452.00	8,160.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	Total of Labour	New	1,692.60	1,667.40
2	Total Paint Including Material	New	957.85	978.20
<b>Supplementary #1</b>				
<b>Labour Items</b>				
3	L/F WHEELHOUSE REPAIR	New	336.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>2,986.45</b>	<b>2,645.60</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >