### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance

(Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Attn: Jacqueline Tan Date: 28 Jan 2022

# **Preliminary Advice**

Vehicle No : SJZ7606B Accident Date : 22/09/2021

Make : HYUNDAI AVANTE Policy No.

DMPCSNW00062352100

Assignment Excess : 27/01/2022 : S\$3,500.00

Date

Date of : 27/01/2022 Est. Duration of

: 14 Inspection Repair

Inspection At: GOLDBELL ENGINEERING PTE LTD (TUAS)

**10 TUAS AVE 18** SINGAPORE 638894

## **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 12,897.45 **Revised Amount** :S\$ 8,392.45 Check Items (Estimated) :S\$ 2,891.00 Total :S\$ 11,283.45

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

:S\$ 28,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 14,632.00 Salvage Value :S\$

Margin for Repair :S\$ 13,368.00

## **Remarks**

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: The vehicle repair on Lump Sum Basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.