



## CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, SINGAPORE 729667

Tel : +65 6467 0956 Fax : +65 6469 4319

Email : [crownasia@hotmail.sg](mailto:crownasia@hotmail.sg)

Company Reg No: 201023449R

3/11/2017

To : First Capital Insurance Ltd

BY FAX ONLY  
(fax no. 65073849)

Attn : Motor claims dept

Dear Sirs ,

We are instructed by M/s A Star Transport Service LLP to notify you of a road traffic accident on 1/11/2017 at about 0750 hrs along Jurong East Avenue 1 involving our customer's motor bus , PA 9349 R and your insured's vehicle YP 6451 L. A copy of the Singapore Accident Statement report is enclosed.

As a result of the accident , our customer's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a per-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline , we shall proceed to repair the vehicle without further reference to you.

Kindly contact our Miss Rochelle (h/p 83036523) for the survey.

Yours faithfully

encl.



# CROWN ASIA BUS BUILDER PTE LTD

44 SUNGAI KADUT AVE, SINGAPORE 729667

Tel : +65 6467 0956 Fax : +65 6469 4319

Email : [crownasia@hotmail.sg](mailto:crownasia@hotmail.sg)

Company Reg No: 201023449R

6/11/2017

First Capital Insurance Ltd  
c/o : Surveyor

Dear Sirs ,

## THIRD PARTY CLAIM – REPAIR ESTIMATE FOR PA 9349 R

Traffic accident on 21/2/2017 involving PA 9349 R , YP 6451 L AND SHD 4640 K ALONG JURONG EAST AVENUE 1.

We append below the repair estimate for PA 9349 R (Isuzu LT 134P))

### Parts required :-

1 pc	Rear bumper	\$ 3800.00
1 pc	Rear right inspection lid cover	\$ 4200.00
2 pcs	Rear right inspection lid cover lock	\$ 180.00
1 pc	Rear right top body panel	\$ 4200.00
		\$12380.00
	Less 10% trade discount	\$ 1238.00
		\$11142.00
1 pc	Rear right window glass gum	\$ 200.00
	Total parts cost	\$11342.00

### Labour charges :-

To remove rear right window glass so as to enable repair to be carried out and refit same.	\$ 300.00
To remove rear right seats, inner trim board etc. so as to enable To be carried out and refit same.	\$ 300.00
To putty and spray painting on rear bumper , rear right body panel, Rear right inspection lid cover and all affected accident parts.	\$ 1800.00
b.c.f.	\$13742.00

...2/-

**CROWN ASIA BUS BUILDER PTE LTD**

**PA 9349 R**

b.b.f. \$13742.00

To straighten rear right body structural frame assy. To knock/  
Straighten all necessary parts including repairing and changing  
Of all damaged parts and align same. \$ 1500.00

Total repair cost \$15242.00

Note :- This estimate is based on visible damage only. Should any hidden parts and/or labour charges required during works in progress , insurer and/or their surveyor will be notified accordingly.

**CROWN ASIA BUS BUILDER PTE LTD**



---

David Liang (H/P 96662662)  
Claims Consultant