

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.

M/S.: MS FIRST CAPITAL INSURANCE LIMITED.
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877

Bill No : FC180113
Our Ref. : FC/1711/PA9394/TP
Date : 16 January 2018

Your Reference : D17010246MFCV
Policy Number : Not Advised
Insured Vehicle : YP 6451L
Third Party's Vehicle : PA 9349R
Date of Accident : 01 Nov 2017
Date of Inspection : 07 Nov 2017
Date of Re-inspection : N/A
Survey conducted at : Crown Asia Bus Builders Pte Ltd

<u>Description</u>	<u>Amount</u>
Pre-repair inspection fees inclusive of Transportation and Pictures (10) Copies	\$ 80.00 \$ \$
Total	\$ <u>80.00</u>

Dollars: Eighty only

L H TEO APPRAISAL SERVICES



Teo Liak Hoo
Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM(Dip.BTM)
MIIE, MIMI, AMSIM

Loss Adjuster, Consulting Automotive Engineer, Accident Reconstruction & Analyst.**PRE-REPAIR INSPECTION REPORT**

M/S: MS FIRST CAPITAL INSURANCE LIMITED.
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877

Our Ref : FC/1711/PA9394/TP
Date : 16 January 2018

Type of Appraisal : Third Party Property Damage
Your Reference : D17010246MFCV
Policy Number : Not Advised
Insured Vehicle : YP 6451L

Assigned by : Vinod
Date of Accident : 01 Nov 2017
Date of Assignment : 02 Nov 2017
Date of Inspection : 07 Nov 2017

PARTICULARS OF THIRD PARTY VEHICLE

Regn. No : PA 9349R
Make : ISUZU
Model : LT134P
Year : 2010 (COE .Exp : Mar 2020)

Odometer : 182451km
Color : White
Chassis No : JALLT134P97000093
Engine No : 6HK1486117

DAMAGE PROFILE

There were damages seen on Rear Right side.

REMARKS

Despite our request we have not been provided with the repair estimate.

Market value of the vehicle at time of accident was \$1, 28,800 approximately

Attached (10) pictures depicting damage to the vehicle.

Survey conducted at: Crown Asia Bus Builders Pte Ltd

Faithfully Yours
L H TEO Appraisal Services



Teo Liak Hoo
Advance Automotive Engineer (UK)
Dip. Mech. Engr. M Prof BTM (Dip.BTM)
MIIE, MIMI, AMSIM