

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22000965/VQY3N2**Date:** 31/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00086892100
Claimant Vehicle No :	SMU5217U	Insured Vehicle No :	GBC8112T
Date of Loss:	21/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200651/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMU5217U	Engine No:	L15B6021824
Make & Model:	HONDA SHUTTLE, 1.5 (A)	Chassis No:	GK82101564
Reg. Date:	17/08/2020 (Man. Year: 2019)	Odometer:	33771 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,946.40	2,760.40	4,186.00	60.26
Miscellaneous Items	0.00	0.00	0.00	
Labour	960.00	960.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,906.40	3,720.40	4,186.00	52.94
Approved Total (Overridden) (\$\$)		3,000.00		
Nett Amount (\$\$)	7,906.40	3,000.00	4,906.40	62.06

INSPECTION

Date of Assignment:	27/01/2022	THE WHEELERS AUTO SERVICES PTE LTD (HQ)
Date Inspected:	28/01/2022 Inspected At:	Block 2 Kaki Bukit Avenue 2 #01-14 Kaki Bukit Autohub
Estimated Period of Repair:	4.0 days	Singapore 417921

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 30 Mar 2022)	
Parts:	N/A	HONDA SHUTTLE 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMU5217U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented	1,155.00 F	*1,155.00 FL
2	1		*FRONT BUMPER RETAINER	Necessary	79.50 F	*79.50 FL
3	1		*FRONT BUMPER CLIP	Necessary	38.00 F	*38.00 FL
4	1		*FRONT BUMPER GARNISH	Serviceable	80.00 F	*- FL
5	1		*FRONT BUMPER RADIATOR GRILLE	Serviceable	425.00 F	*- FL
6	1		*LEFT HAND FENDER	Repair	495.00 F	*- FL
7	1		*LEFT HAND INNER SHIELD	Serviceable	125.90 F	*- FL
8	1		*LEFT HAND INNER SHIELD CLIP	Necessary	28.00 F	*28.00 FL
9	1		*LEFT HAND FRONT HEADLAMP	Cracked	2,150.00 F	*2,150.00 FL
10	1		*LEFT HAND FRONT SUSPENSION	Serviceable	320.00 F	*- FL
11	1		*LEFT HAND LOWER ARM	Serviceable	330.00 F	*- FL
12	1		*LEFT HAND FRONT WHEEL KNUCKLE	Serviceable	600.00 F	*- FL
13	1		*LEFT HAND WHEEL BEARING	Serviceable	120.00 F	*- FL
14	1		*LEFT HAND SPORT RIMS	Serviceable	1,000.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,946.40	3,450.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	690.10
Total Parts (\$\$)	6,946.40	2,760.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	500.00	500.00
2	SPRAY PAINT	New	400.00	400.00
3	TO REMOVE AND REFIX UNDERCARRIAGE (NPA)	New	0.00	0.00
4	TO CHECK WIRING	New	30.00	30.00
5	WHEEL ALIGNMENT (NPA)	New	0.00	0.00
6	RUST PROOF	New	30.00	30.00
Gross Labour Cost (\$\$)			960.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >