



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000966/Kvf3q2	
			Date: 21/03/2022	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBJ 6190T	Veh. Inspected	SLD 8930A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200371/GPL	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	27/01/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 2 (A)	c.c	2016
	Engine No.	HIDDEN	Year of Reg.	1496
	Chassis No.	MM6DL2SAAGW185601	Colour	METALLIC PEARL WHITE
	Odometer	56059 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	185/60 R16	YOKOHAMA	8 mm
	L/H Front Tyre	185/60 R16	YOKOHAMA	8 mm
	R/H Rear Tyre	185/60 R16	YOKOHAMA	8 mm
	L/H Rear Tyre	185/60 R16	YOKOHAMA	8 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	26/01/2022	Inspection Date	28/01/2022
	Survey held at	ELITE AM PTE. LTD. 280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST @ WOODLANDS, 757322 WOODLANDS		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	