

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000969/Vvy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 14/02/2022 SINGAPORE 068811 ATTN: KHONG LYNN Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLZ 8758R** SJQ 579P Veh. Inspected Policy No. GA541604 Coverage (\$) 0.00 Claim No. S2M03S1F Excess (\$) 0.00 KHONG LYNN **Assign Date** 27/01/2022 Assign From **Vehicle Particulars & Condition** 2. TOYOTA COROLLA ALTIS Make & Model 1598 C.C HIDDEN 2009 Engine No. Year of Reg. MR053ZEE106143270 **BROWN** Chassis No. Colour 199087 KM Odometer Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 195/65 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 195/65 R15 6 mm 195/65 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 195/65 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. 5. **General Information** 27/01/2022 Inspect Date / Time 28/01/2022 (11:30 AM) Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000

Report Ref No. CS3/ASM22000969/Vvy3e2

**Estimate Days of Repair** 

**Inspected By** 

5b.

THEVAN THOMAS KARTHIKESAVAN

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

6 Working Days