



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 2854H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT FENDER RH	TO REPAIR SEE LABOUR	452.00	-
1	FRONT FENDER INNER EMBLEM RH	NECESSARY	42.00	42.00
1	HEADLAMP RH	CUT	1,985.00	1,985.00
	LESS 20% DISCOUNT		-495.80	-405.40
			1,983.20	1,621.60
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT WHEEL HUB CAP RH (SN)	SERVICEABLE	80.00	-
			80.00	-
	<u>LABOUR</u>			
	TO CHECK ELECTRICAL WIRING.		80.00	20.00
	CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	15.00	-
	TO RESPRAY UNDERCOATING.	NOT NECESSARY	300.00	-
	APPLY ANTI RUST ON AFFECTED AREAS.	NOT NECESSARY	200.00	-
	SPRAY PAINTING ON AFFECTED AREAS.		400.00	360.00
	PANEL BEATING ON AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT FENDER RH.		400.00	200.00
			1,395.00	580.00
GRAND TOTAL			3,458.20	2,201.60
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CS/SMO22000972/Ktf3n2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.