#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG22000979/KQF3E2

**Date:** 01/08/2022

**REFERENCE** 

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: 30001929238

Claimant Vehicle

No: SKQ6865L Insured Vehicle No: GBH4977P

Date of Loss: 26/01/2022 Nature of Claim: TP Claim No: 269191

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKQ6865L

 Make & Model:
 KIA FORTE K3, 1.6 (A)
 Engine No:
 G4FGEH748600

 Reg. Date:
 19/12/2014 (Man. Year: 2014)
 Chassis No:
 KNAFZ411MF5349152

Colour: Metallic Grey Odometer: 89473 km

Engine Capacity: 1591 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45Z R17 Rear Tyre Size: 215/45Z R17
Front Left Side: Roadstone 6 mm Rear Left Side: Goodyear 2 mm
Front Right Side: Roadstone 6 mm Rear Right Side: Goodyear 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		4,799.04	2,585.94	2,213.10	46.12
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,650.00	1,220.00	430.00	26.06
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	6,449.04	3,805.94	2,643.10	40.98
	Approved Total (Overridden) (S\$)		3,000.00		
	(S\$)	6,449.04	3,000.00	3,449.04	53.48
	+ GST 7.00/7.00% (S\$)	451.43	210.00	241.43	53.48
	Nett Amount (S\$)	6,900.47	3,210.00	3,690.47	53.48

**INSPECTION** 

Date of Assignment: 27/01/2022

Cheng Hoe Motor Pte Ltd (AMK)

Date Inspected: 14/03/2022 Inspected At: 10 ANG MO KIO IND PARK 2A, #01-04 ANG MO

KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## **REPAIR DETAILS**

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Jun 2022)

Parts: 143 KIA FORTE K3 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKQ6865L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	6		*FRONT BUMPER CLIP	Necessary	28.80 FL	*28.80 FL
2	1		*FRONT LH FENDER	Bent	377.00 FL	*377.00 FL
3	1		*FRONT LH FENDER INNER SHIELD	Cracked	81.00 FL	*81.00 FL
4	6		*FRONT LH FENDER INNER SHIELD CLIP	Necessary	28.80 FL	*28.80 FL
5	1		*HEADLAMP LH	Serviceable	1,795.00 FL	*- FL
6	1		*FRONT LH DOOR	Bent	1,355.00 FL	*1,355.00 FL
7	1		*FRONT LH DOOR FRAME STICKER	Necessary	46.00 FL	*46.00 FL
8	1		*FRONT LH DOOR TOP HINGE	Repair	33.00 FL	*- FL
9	1		*FRONT LH DOOR CHECKER	Serviceable	46.00 FL	*- FL
10	1		*FRONT LH DOOR BOTTOM HINGE	Repair	34.00 FL	*- FL
11	1		*FRONT LH RIM	Dented	790.00 FL	*790.00 FL
12	1		*FRONT LH KNUCKLE ARM	Serviceable	420.00 FL	*- FL
13	1		*FRONT LH WHEEL BEARING	Not Necessary	131.00 FL	*- FL
14	1		*SET DOOR VISOR	Necessary	150.00 FS	*150.00 FS
F=Fra	nchise	part. S=SpcN	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	5,315.60	2,856.60
			- List Item Discount on L	Items 10.00/10.00% (S\$)	516.56	270.66
				Total Parts (S\$)	4,799.04	2,585.94
				-		

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REMOVE & REFIX FRT BUMPER & ATTACHMENTS, HEADLAMP, FRT LH FENDER, FRT LH DOOR & ATTACHMENTS; KNOCKING & REPAIR FRT LH DOOR PILLAR & REALIGN THE SAME	New	600.00	450.00
2	PUTTY & RESPRAY FRT BUMPER, FRT LH FENDER, FRT LH DOOR & PILLAR & ALL AFFECTED AREAS	New	700.00	600.00
3	REMOVE & REFIX FRT WHEEL, KNUCKLE ARM, BEARING & REALIGN THE SAME	New	180.00	0.00
4	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
5	REMOVE & REFIX FRT LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	New	50.00	50.00
6	RUSTPROOFING	New	60.00	60.00
	Gross Labour	Cost (S\$)	1,650.00	1,220.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >