

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GY 5953C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER (CONSISTENT)	CUT	595.32	595.32
1	FRONT BUMPER RETAINER LH (CONSISTENT)	NECESSARY	79.00	79.00
1	FRONT BUMPER COVER LH (CONSISTENT)	NOT NECESSARY	104.00	-
1	FRONT STEP GARNISH LH (CONSISTENT)	SCRATCHED	69.84	69.84
1	FRONT STEP PANEL LH (CONSISTENT)	SCRATCHED	178.09	178.09
1	FRONT HEADLAMP LH (CONSISTENT)	SCRATCHED	818.40	589.00
1	FRONT HEADLAMP BRACKET LH (CONSISTENT)	CUT	128.30	128.30
1	FRONT DOOR PANEL LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,778.90	-
2	FRONT DOOR HINGE (CONSISTENT)	SERVICEABLE	68.00	-
	LESS 25% DISCOUNT		-954.96	-409.89
			2,864.89	1,229.66
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	30.00	20.00
1	DOOR COMPANY DECAL (SN) (CONSISTENT)	NECESSARY	80.00	30.00
			110.00	50.00
	<u>LABOUR</u>			
	CHECK WIRING AND LIGHTING SYSTMEM.		60.00	20.00
	REMOVE AND REFIT DOOR MECHANISM FOR REPAIR.	NOT NECESSARY	200.00	-
	PANEL BEATING ON AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRONT DOOR PANEL LH .		800.00	500.00
	SPRAY PAINTING ON AFFECTED AREAS .		800.00	300.00
	APPLY ANTI RUST ON AFFECTED AREAS .		150.00	30.00
			2,010.00	850.00
	GRAND TOTAL		4,984.89	2,129.66



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,700.00
TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22000980/Vga3q2



THEVAN THOMAS KARTHIKESAVAN

**Asst. Automotive Assessor** 



**HO LEONG CHUAN** 

**Automotive Assessor**