

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG22000984/AGVF3N2**Date:** 15/06/2022REFERENCE

|                              |                                      |                             |            |
|------------------------------|--------------------------------------|-----------------------------|------------|
| Handling Insurer:            | MSIG Insurance (Singapore) Pte. Ltd. | Policy No:                  | 1001867314 |
| <b>Claimant Vehicle No :</b> | SMM1910U                             | <b>Insured Vehicle No :</b> | FBS8857T   |
| Date of Loss:                | 27/01/2022                           | Nature of Claim:            | TP         |
|                              |                                      | Claim No:                   | 269205     |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SMM1910U</b>                   | Engine No:  | R16B25510304      |
| Make & Model:               | HONDA CIVIC, 1.6 VTI CVT (A)      | Chassis No: | MRHFC5650KT000320 |
| Reg. Date:                  | 20/06/2019 (Man. Year: 2019)      | Odometer:   | 51813 km          |
| Colour:                     | Grey                              |             |                   |
| Engine Capacity:            | 1597 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |             |                  |             |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size:  | 215/55R16   | Rear Tyre Size:  | 215/55R16   |
| Front Left Side:  | Dunlop 6 mm | Rear Left Side:  | Dunlop 6 mm |
| Front Right Side: | Dunlop 6 mm | Rear Right Side: | Dunlop 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 2,123.68          | 1,039.20          | 1,084.48          | 51.07         |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 2,400.00          | 750.00            | 1,650.00          | 68.75         |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>4,523.68</b>   | <b>1,789.20</b>   | <b>2,734.48</b>   | <b>60.45</b>  |

INSPECTION

|                             |                          |                                                     |
|-----------------------------|--------------------------|-----------------------------------------------------|
| Date of Assignment:         | 28/01/2022               | Hua Meng Spray Painting Workshop (HQ)               |
| Date Inspected:             | 08/02/2022 Inspected At: | No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit |
| Estimated Period of Repair: | 3.0 days                 | Singapore 417883                                    |

**Adjuster:** XING GUO QIANG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

|               |                                                                                                                                                                              |                                                               |
|---------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------|
| Reference     |                                                                                                                                                                              |                                                               |
| Part Source:  | MRM-SG                                                                                                                                                                       | Version: 1.0 (Last Synchronised: 14 Jun 2022)                 |
| Parts:        | 143                                                                                                                                                                          | HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour:       | Repairer's                                                                                                                                                                   | (Price-denominated Standard List)                             |
| Print Code:   | (Unsubmitted, no print-code for SMM1910U)                                                                                                                                    |                                                               |
| Validity:     | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |                                                               |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *.                                                                                                     |                                                               |

Recommended Parts

| No. | Qty | Part No. | Particulars                      | Condition     | Repairer's | Amount     |
|-----|-----|----------|----------------------------------|---------------|------------|------------|
| 1   | 1   |          | *REAR BOOTLID                    | Not Necessary | 554.90 FL  | *- FL      |
| 2   | 1   |          | *REAR BOOTLID H EMBLEM           | Not Necessary | 29.20 FL   | *- FL      |
| 3   | 1   |          | *REAR BOOTLID CIVIC EMBLEM       | Not Necessary | 38.20 FL   | *- FL      |
| 4   | 1   |          | *REAR BUMPER                     | Deformed      | 677.20 FL  | *677.20 FL |
| 5   | 2   |          | *REAR BUMPER SIDE HOLDER         | Necessary     | 57.40 FL   | *57.40 FL  |
| 6   | 1   |          | *REAR BUMPER LOWER LIP           | Deformed      | 198.70 FL  | *198.70 FL |
| 7   | 1   |          | *REAR BUMPER LOWER LIP PROTECTOR | Cut           | 78.20 FL   | *78.20 FL  |
| 8   | 1   |          | *REAR BUMPER TOWING HOOK COVER   | Not Necessary | 38.00 FL   | *- FL      |
| 9   | 1   |          | *REAR BUMPER REINFORCEMENT       | Not Necessary | 280.00 FL  | -          |
| 10  | 1   |          | *REAR END PANEL                  | Repair        | 277.80 FL  | *- FL      |
| 11  | 1   |          | *SET REAR BUMPER REVERSE SENSOR  | Damaged       | 280.00 FS  | *200.00 FS |
| 12  | 1   |          | *SET REAR BUMPER CLIPS           | Necessary     | 60.00 FS   | *30.00 FS  |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                     |          |          |
|-----------------------------------------------------|----------|----------|
| Sub Total (\$\$)                                    | 2,569.60 | 1,241.50 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 445.92   | 202.30   |
| Total Parts (\$\$)                                  | 2,123.68 | 1,039.20 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No                            | Particulars                                        | Lab.Type | Repairer's      | Amount        |
|-------------------------------|----------------------------------------------------|----------|-----------------|---------------|
| <b>Labour Items</b>           |                                                    |          |                 |               |
| 1                             | TO SUPPLY REAR END PANEL INNER SEALANT             | New      | 50.00           | 0.00          |
| 2                             | REMOVE & REFIX REVERSE SENSOR                      | New      | 150.00          | 50.00         |
| 3                             | REMOVE & REFIX BOOTLID GARNISH                     | New      | 200.00          | 0.00          |
| 4                             | REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT | New      | 1,000.00        | 300.00        |
| 5                             | RESPRAY PAINTING                                   | New      | 1,000.00        | 400.00        |
| <b>Gross Labour Cost (\$)</b> |                                                    |          | <b>2,400.00</b> | <b>750.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >