LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd Our File No: CS/III22000985/ANF3E2 64 Cecil Street, #04-00 IOB Building

Date: 05/08/2022 Singapore 049711

REFERENCE

Insured/Claimant: COMFORTDELGRO DRIVING CENTRE PTE LTD

D20MFL0000618-Policy No:

02

Nature of Claim Date of Loss: 26/01/2022 OD MFL2022D0000542 Claim: No:

DESCRIPTION & IDENTIFICATION OF VEHICLE

SND2113H Reg No:

Make & Model: TOYOTA COROLLA, 1.5 AXIO (M) Engine No: 1NZ9331039 Reg. Date: 14/12/2021 (Man. Year: 2021) Chassis No: NZE1617133790

Colour: Silver Odometer:

1496 cc **Engine Capacity:** Market Value/New Car Price: S\$100.000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): Yes **Engine Modification:** Nο Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R15 Rear Tyre Size: 175/65 R15 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,762.95	1,590.45	172.50	9.78
Miscellaneous Items		130.00	80.00	50.00	38.46
Labour		1,550.00	1,130.00	420.00	27.10
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	3,442.95	2,800.45	642.50	18.66
	- Excess (S\$)	0.00	500.00	-500.00	
	(S\$)	3,442.95	2,300.45	1,142.50	33.18
	+ GST 7.00/7.00% (S\$)	241.01	161.03	79.98	33.19
	Nett Amount (S\$)	3,683.96	2,461.48	1,222.48	33.18

INSPECTION

Date of Assignment: 28/01/2022 Present Location: Kang Car Repairers Pte Ltd (HQ)

Kang Car Repairers Pte Ltd (HQ)

845 km

No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Date Inspected: 28/01/2022 Inspected At:

Bukit

Singapore 417883

Estimated Period of Repair: 4.0 days

ADRIAN LING Manager: **HUEY YON** Adjuster:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Aug 2022)

Parts: 143 TOYOTA COROLLA 1.5 AXIO (M) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SND2113H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH (WCP)	Dented	250.00 F	*250.00 F
2	1		*FRONT FENDER COWLING LH (WCP)	Deformed	105.00 F	*105.00 F
3	1		*HEAD LAMP LH (WCP)	Cracked	340.00 F	*340.00 F
4	1		*FRONT BUMPER (WCP)	Distorted	700.00 F	*550.00 F
5	1		*FRONT BUMPER SIDE RETAINER LH (WCP)	Missing	58.00 F	*58.00 F
6	1		*FRONT BUMPER FOG LAMP COVER LH (WCP)	Deformed	80.00 F	*80.00 F
F=Fra	anchise	part.		Sub Total (S\$)	1,533.00	1,383.00
			+ Margin on L,N It	tems 15.00/15.00% (S\$)	229.95	207.45
				Total Parts (S\$)	1,762.95	1,590.45
			Report was unsubmitted during	this print-out.		

Recommended Miscellaneous Items

No	Qty	Particulars		Repairer's	Amount		
Mis	liscellaneous Items						
1	1	FRONT BUMPER CLIPS (NECESSARY)		60.00	30.00		
2	1	FRONT FENDER COWLING CLIPS (NECESSARY)		40.00	20.00		
3	1	FRONT FENDER NUMBER 720 STICKER (NECESSARY)		30.00	30.00		
			Sub Total (S\$)	130.00	80.00		

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY PAINTING (FRONT)	New	800.00	600.00
3	TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS AND FOR CUTTING/WELDING WORKS	New	700.00	500.00
	Gross Labor	ur Cost (S\$)	1,550.00	1,130.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >