



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 1044P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	BACK SENSOR SILVER METALLIC 1F (SN)	BROKEN	173.10	173.10
1	ANTENNA, ELECTRICAL (SN)	NOT NECESSARY	76.30	-
1	LENS & BODY, RR (SN)	NOT NECESSARY	479.30	-
1	LENS & BODY, RR (LH UPPER) (SN)	CUT	469.90	469.90
1	COVER, RR (SN)	NOT NECESSARY	68.50	-
1	COVER, RR (SN)	NOT NECESSARY	68.50	-
1	LENS & BODY, RR (SN)	NOT NECESSARY	532.00	-
1	LENS & BODY, RR (LH LOWER) (SN)	CUT	532.00	532.00
1	COVER, RR BUMPER (SN)	DENTED	469.50	469.50
1	GUARD, RR BUMPER (SN)	CUT	611.30	611.30
1	FILLER, RR BUMPER	NOT NECESSARY	131.10	-
1	FILLER, RR BUMPER (SN)	NOT NECESSARY	131.10	-
10	PIECE, RR BUMPER (SN)	NECESSARY	48.00	43.50
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	124.90	-
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	123.60	-
1	REINFORCEMENT (SN)	DENTED	353.10	353.10
1	GARNISH SUB-ASSY (SN)	TO REPAIR SEE LABOUR	984.40	-
1	SPOILER SUB-ASSY, RR (SN)	BROKEN	1,668.60	1,668.60
1	LAMP SET, STOP CTR (SN)	BROKEN	203.90	203.90
1	GLASS SUB-ASSY, BACK (SN)	NOT NECESSARY	805.80	-
			8,154.90	4,574.90
	<u>LABOUR</u>			
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.		180.00	180.00
	R/I REAR REVERSE SENSOR TO FACILITATE REPAIRS AND TST FUNCTION.		180.00	180.00
	R/I REAR TOP SPOILER AND ATTACHMENT TO FACILITATE REPAIRS.		180.00	180.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF GARNISH SUB-ASSY. TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.		3,600.00	1,080.00
			2,950.00	1,180.00
			7,270.00	2,980.00
GRAND TOTAL			15,424.90	7,554.90
RECOMMENDED COST OF REPAIRS				7,554.90

Report Ref No. CS/FCI22000986/Etf3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.