



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMX 3719K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAIL GATE 'FIT' EMBLEM	NECESSARY	66.00	66.00
1	REAR TAIL GATE INNER TRIM	SCRATCHED	338.90	285.00
1	REAR O/S TAIL LAMP	CRACKED	497.60	497.60
1	REAR O/S TAIL GATE LAMP	CRACKED	465.00	465.00
1	REAR WINDSCREEN	CRACKED	1,309.00	1,150.00
	LESS 20% DISCOUNT		-535.30	-492.72
			2,141.20	1,970.88
<u>SPECIAL NETT ITEMS</u>				
8	REAR TAIL GATE INNER TRIM CLIPS (SN)	NECESSARY	24.00	12.00
1	REAR WINDSCREEN MOULDING (SN)	NECESSARY	160.00	110.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR SOLAR FILM (SN)	NECESSARY	150.00	100.00
1	DASH CAMERA (SN)	SERVICEABLE	800.00	-
			1,214.00	262.00
<u>LABOUR</u>				
	TO REMOVE AND REFIT REAR DAMAGE PARTS.		400.00	200.00
	TO SPRAY PAINTING.		500.00	400.00
	TO REMOVE AND REFIT REAR WINDSCREEN.		160.00	120.00
	TO CHECK WIRING.		80.00	30.00
			1,140.00	750.00
GRAND TOTAL			4,495.20	2,982.88
RECOMMENDED COST OF REPAIRS				2,982.88

Report Ref No. CS/UOI22000987/Vvf3e2

THEVAN THOMAS KARTHIKESAVAN

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.