

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	UNITED OVERSEA	AS INSURANCE LTD		Ref:	CS/UOI22000987/Vvf3e2	
	146 ROBINSON RO #02-01 UOI BUILD	OAD INGSINGAPORE 068909		Date:	22/02/2022	
				Code:	UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBL 4629Z	Veh. Inspected	d	SMX 3719K	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	M12D17652202	Excess (\$)		0.00	
	Assign From	JOSEPHINE WONG	Assign Date		28/01/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA FIT 1.3	c.c		1317	
	Engine No.	HIDDEN	Year of Reg.		2021	
	Chassis No.	GR11010634	Colour		RED	
	Odometer	20583 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	BRIDGESTONE		7 mm	
	L/H Front Tyre	195/65 R15	BRIDGESTONE		7 mm	
	R/H Rear Tyre	195/65 R15	BRIDGESTONE		7 mm	
	L/H Rear Tyre	195/65 R15	BRIDGESTONE		7 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/01/2022	Inspection Date	te	28/01/2022	
	Survey held at	RYDER AUTO PTE LTD				
		2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					