2/25/22, 3:27 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22000988/EVY3N2

25/02/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMB1SNW00014432000

Claimant Vehicle

PA6559X

Insured Vehicle No: PC203B

No: Date of Loss: 25/01/2022

Nature of

Claim:

TP

Claim SNM22D200686/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

PA6559X Reg No:

MITSUBISHI BE639GRMHDEA, 3.9 D (M) Make & Model: Engine No: 4D34K93100 Reg. Date: 26/09/2006 (Man. Year: 2006) Chassis No: BE639JD00379 Colour: Multi-colour Odometer: 931777 km

Engine Capacity: 3908 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 215/75R17.5 Rear Tyre Size: 215/75R17.5 Front Left Side: Rear Left Side: Dunlop 4 mm Dunlop 4 mm Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,485.00	6,861.75	8,623.25	55.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,130.00	3,830.00	1,300.00	25.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,615.00	10,691.75	9,923.25	48.14
Approved Total (Overridden) (S\$)		8,550.00		
(S\$)	20,615.00	8,550.00	12,065.00	58.53
+ GST 7.00/7.00% (S\$)	1,443.05	598.50	844.55	58.53
Nett Amount (S\$)	22,058.05	9,148.50	12,909.55	58.53

INSPECTION

Date Inspected:

Date of Assignment: 15/02/2022

Woodlands Transport Service Pte Ltd (HQ)

28/01/2022 Inspected At: 8 Gul Circle

Singapore 629564

Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

2/25/22, 3:27 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Feb 2022)

Parts: N/A MITSUBISHI BE639GRMHDEA 3.9 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for PA6559X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	2,000.00 F	*1,900.00 FL
2	1		*REAR RHS DOOR	Dented	4,000.00 F	*2,654.00 FL
3	1		*REAR LHS DOOR	Dented	4,000.00 F	*2,654.00 FL
4	1		*REAR RHS DOOR GLASS	Broken	350.00 F	*350.00 FL
5	1		*REAR RHS DOOR GLASS RUBBER	Necessary	200.00 F	*200.00 FL
6	1		*REAR LHS CORNER PANEL	Dented	4,500.00 F	*1,236.00 FL
7	1		*60KM STICKER	Necessary	5.00 F	*5.00 FL
8	1		*REAR NUMBER PLATE	Not Necessary	30.00 F	*- FL
9	1		*WOODLANDS TRANSPORT REAR STICKER	Necessary	150.00 F	*150.00 FL
10	1		*CHILDREN TRIANGLE CROSS SIGN	Not Necessary	250.00 F	*- FL
F=Fra	anchise	part. L=ListIte	emDisc.	_		
				Sub Total (S\$)	15,485.00	9,149.00
			- List Item Discount on L Items 0.00/25.00% (S\$)			2,287.25
				Total Parts (S\$)	15,485.00	6,861.75
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE AND RE-INSTALL REAR PASSENGER SEATS FOR FACILITATE REPAIR REAR BOTH SIDE DOOR PANEL AND CORNER PANEL	New	500.00	200.00
2	TO DISMANTLE DAMAGED PARTS TO REPAIR AND REPLACE BOTH SIDE DOOR, REAR BUMPER AND CORNER PANEL	New	2,000.00	1,800.00
3	TO CHECK WIRING AND INSTALL CHILDREN CROSS SIGN	New	180.00	30.00
4	TO REMOVE DAMAGED PARTS AND INSTALL REAR RHS DOOR GLASS WITH RUBBER	New	250.00	200.00
5	TO SPRAY PAINTING REAR BUMPER,REAR BOTH SIDE DOOR PANEL AND REAR LHS CORNER PANEL	New	2,200.00	1,600.00
	Gross Labour Cost (S\$)		5,130.00	3,830.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >