

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKU 9660U

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR D4	DENTED	2,326.60	2,326.60
1	BUMPER PAD MOULDING	CUT	215.90	215.90
1	BUMPER MOULDING TOW	CUT	130.00	130.00
1	BUMPER FOAM REAR DIS	NOT NECESSARY	126.10	-
1	BUMPER REFLECTOR REAR	BROKEN	194.90	194.90
1	BUMPER REFLECTOR REAR	NOT NECESSARY	194.90	-
4	PARKING AID 90 DEGRE @\$367.20	NOT NECESSARY	1,468.80	-
1	BUMPER BRACKET REAR	NOT NECESSARY	143.50	-
1	BUMPER BRACKET REAR	NOT NECESSARY	143.50	-
1	BUMPER BRACKET REAR	NOT NECESSARY	108.20	-
1	BUMPER BRACKET REAR	NOT NECESSARY	108.20	-
1	BUMPER BRACKET REAR	NOT NECESSARY	139.10	-
1	BUMPER BRACKET REAR	NOT NECESSARY	126.40	-
15	GRILLE CLIP EVOQUE @\$4.00	NECESSARY	60.00	60.00
10	BUMPER BRACKET NUT R @\$4.10	NECESSARY	41.00	41.00
1	LH CTR SENSOR BRACKE	NOT NECESSARY	18.60	-
1	PDC HOLDER REAR LH D	NOT NECESSARY	20.40	-
	LESS 10% DISCOUNT		-	-296.84
			5,566.10	2,671.56
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER, REAR BUMPER PAD, REAR BUMPER LOWER, REAR REFLECTOR LH, ETC.		1,500.00	1,300.00
	TO SPRAY REAR BUMPER.		1,200.00	1,000.00
	TO CHECK WIRING INCLUDE RESETTINNG OF ALL ELECTRICAL MODULES.		621.00	621.00
			3,321.00	2,921.00
	GRAND TOTAL		8,887.10	5,592.56

Report Ref No. CS/FCI22000989/Evf3e2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS 5,592.56

Report Ref No. CS/FCI22000989/Evf3e2



Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser