



CYCLE & CARRIAGE

**CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE**

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL:67143369 Contact No	Cust No/Name	KCV17595/Mr Mandapati Venkata Satya Kira
	Reg No/Reg Date	SLP6932U*# / 15/06/2017
	Date In/Mileage	19/01/2022/ 64434
	Chassis No	JMYXTGF3WHZ002287
	Engine No	4B12TC3024
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F58)
	Colour/Trim	D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000051	Credit	28/01/2022/ 09:24	OD	303 / Renemer	25532

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
S MIPNT88088 DIAGNOSTIC/SCANNING				200 250.00
S MIPNT88088 TO CHECK ALL LIGHTING/WIRING SYSTEM ON LHR ACCIDENT AFFECTED AREAS				80 100.00
S MIPNT88088 TO REPLACE TAILGATE GLASS AND MOULDINGS				240 300.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW TAILGATE GLASS				80 100.00
S MIPNT88088 TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS & LH QTR GLASS				net 370.00
S MIPNT88088 TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS				320 640.00
S MIPNT88088 TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING/ROOF LINING TO FACILITATE REPAIR ON LHR ACCIDENT AFFECTED AREAS				640 640.00
S MIPNT88088 TO APPLY SEALANT KIT ON NEW & REPAIR BODY PANELS				160 300.00
S MIPNT88088 TO REMOVE & RE-INSTALL FUEL TANK TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS				260 320 640.00 X
S MIPNT88088 TO REPLACE LOGO, TAILLAMPS, TAILGATE, GARNISH, MLDGS, CLIPS, BRACKETS, REAR BUMPER, LH QTR GLASS, WIRING HARNESS, ETC				2880 5120.00
-TO CUT & WELD LH QTR PANEL, LH UPR & LWR EXTENSION PANEL, RR END PANEL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS	640 x 4.5'			510
S MIPNT98088 SPRAY PAINTING ON LHR ACCIDENT AFFECTED AREAS (TAILGATE, REAR BUMPER, LH QTR PNL, UPR & LWR EXTENSION PNL, RR END PANEL)				2200 3200.00
S MIPNT88088 REVERSE SENSOR (ITEMS & INSTALLATION INCLUDED)				280.00
M SUNDRY C & C LOGO				net 50.00
M JJ5805A758 GLASS, TAILGATE WINDO	sketch 1.00	551.00	0.00	551.00

Confirm & accepted by

Authorized signatory and company stamp

7500

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Table with Invoice Name & Address and Owner Name & Vehicle Info. Includes details like ALLIANZ INSURANCE SINGAPORE PTE LTD, KCV17595/Mr Mandapati Venkata Satya Kira, and vehicle specifications.

Table with Account No, Terms, Date/Time Printed, CSE, Operator, and WIP No. Values include F0000051, Credit, 28/01/2022/ 09:24, OD, 303 / Renemer, 25532.

Main table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists various car parts like UPR DAM, TAILGATE, SIDE DAM, TAILGATE, etc., with handwritten notes and checkmarks.

Confirm & accepted by

16041

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Table with 2 main columns: Invoice Name & Address, Owner Name & Vehicle Info. Includes details for ALLIANZ INSURANCE SINGAPORE PTE LTD and vehicle information for a Mitsubishi Outlander.

Table with 6 columns: Account No, Terms, Date/Time Printed, CSE, Operator, WIP No. Row 1: F0000051, Credit, 28/01/2022/ 09:24, OD, 303 / Renemer, 25532

Table with 5 columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Lists parts like PANEL, RR END, LH REINFORCEMENT, RR, etc.

Z NOTES

ACCIDENT ON 19/01/2022 ALONG PAYA LEBAR TOWARDS KPE BEF BUS STOP
OWNER CLAIMING OWN POLICY
EXCESS AND AUTHORIZATION WILL BE ADVISE BY THE INSURANCE COMPANY

Estimate

Handwritten notes: not Authorized, LKK, 28/1/22, P/P \$13721, Excess \$600, 10 days, Tel: 62583561

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
Acknowledged by Repairer
Signature:
Date:

7820

Summary table with 2 columns: Description (Confirm & accepted by, Parts, Labour, Standard Menu, Specialist Job, Others(Lub,etc), Sundry, Total(w/o GST)) and Amount (8,890.00, 0.00, 0.00, 11,940.00, 0.00, 50.00, 20,880.00)

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.