



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 9630S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT CORNER PANEL	CRACKED / DEFORMED	375.00	375.00
1	FRONT HEADLAMP ASSY	DEFORMED	650.00	650.00
1	FRONT SIGNAL LAMP	CRACKED / DEFORMED	275.00	208.00
1	FRONT BUMPER ASSY	WARPED / DEFORMED	650.00	650.00
1	FRONT BUMPER SIDE GARNISH	WARPED / DEFORMED	220.00	170.00
1	FRONT GRILLE	NOT NECESSARY	340.00	-
4	FRONT GRILLE CLIPS	NOT NECESSARY	40.00	-
	LESS 10% DISCOUNT		-255.00	-
	LESS 25% DISCOUNT		-	-513.25
			2,295.00	1,539.75
	<u>SPECIAL NETT ITEMS</u>			
1	NUMBER PLATE (SN)	NOT NECESSARY	65.00	-
1	SIDE MIRROR WITH ROUND MIRROR ASSY (SN)	BROKEN	450.00	300.00
			515.00	300.00
	<u>LABOUR</u>			
	TO RENEW DAMAGED PARTS,STRAIGHTEN AND REPAIR FRONT CHASSIS MEMBER,FRONT FENDER,FRONT DOOR AND ALIGNED ALL PARTS.		1,600.00	400.00
	TO CHECK WIRING FUNCTIONS & CONDUCT WATER LEAKAGE TEST.		180.00	30.00
	TO PUTTY,APPLY PRIMER & SPRAY-PAINT THE AFFECTED AREAS.		1,400.00	300.00
	TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS.		180.00	40.00
			3,360.00	770.00
	GRAND TOTAL		6,170.00	2,609.75



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	-----------------

Report Ref No. CS3/AIG21010221/Rvf3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.