

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

Report Ref : TP21090035

Date: 13 JAN 2022

Wan Sern Metal Industries Pte Ltd
c/o Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

THIRD PARTY SURVEY ACCIDENT OCCURED ON 30 SEP 2021

Workshop Name and Address

Eng Soon Painting SVC
Blk 4 Yew Tee Ind Est 393 - J
Woodlands Road
Singapore 677969

As per your instruction dated 26 Oct 2021
We have carried out a physical inspection on the said
We enclosed herewith our report and findings as follows:

with regard to the above matter.
GBF9630S

1. VEHICLE PARTICULARS

Registration No : GBF9630S
Model : MITSUBISHI CANTER
Year / Capacity : APR 2017/ 2998 cc
Chassis No : FEA01BA20519

Engine No : 4P10C48879
Mileage : 158 672 km
Colour : White

2. TYRES CONDITION

	<u>Size</u>	<u>Made</u>	<u>Balance</u>	<u>Rim</u>
FRONT O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR O/S :	195/50/R15	Bridgestone	9.00 mm	Normal
FRONT N/S :	195/50/R15	Bridgestone	9.00 mm	Normal
REAR N/S :	195/50/R15	Bridgestone	9.00 mm	Normal

AUTOMAX SURVEY

Blk 110 Bedok Reservoir Road , #07-280, Singapore 470110

Mobile : 9855 6879

Email : automaxsurvey@gmail.com

Registration No. 53110062J

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the Front portion(s). For more detail of the damages, please see photograph attached.

4. Estimated normal period of repair : 06 working days to complete

5. In accordance to your instruction, we have Not Authorised repair to the vehicle and the survey done on a "Without Prejudice" basis. We hope that this report will be of assistance to you in dealing with the matter.

6. Should you discover any discrepancy in the report, please kindly notify us within 1 week, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle Number : GBF9630S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

List Items

1 pc	Front corner panel	Cracked / deformed	\$ 375.00	\$ 375.00
1 pc	Front headlamp assy	deformed	\$ 650.00	\$ 650.00
1 pc	Front signal lamp	Cracked / deformed	\$ 275.00	\$ 275.00
1 pc	Front bumper assy	Warped / deformed	\$ 650.00	\$ 650.00
1 pc	Front bumper side garnish	Warped / deformed	\$ 220.00	\$ 220.00
1 pc	Front Grille	distorted	\$ 340.00	\$ 340.00
4 pcs	Front Grille Clips	necessary	\$ 40.00	\$ 40.00

List Parts Sub-Total	\$	2,550.00	\$	2,550.00
Less 10% discount	\$	255.00	\$	255.00
Discounted sub-total	\$	2,295.00	\$	2,295.00

Vehicle Number : GBF9630S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
-----	-------------------	-----------	---------------------------------	------------------------------------

Special Nett Items

1 pc	Number plate	necessary	\$ 65.00	\$ 65.00
1 pc	Side mirror with round mirror assy	broken	\$ 450.00	\$ 450.00

Special Nett Sub-Total	\$	515.00	\$	515.00
Spare Parts Total	\$	2,810.00	\$	2,810.00

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
	Spare PartsTotal c/f	\$ 2,810.00	\$ 2,810.00
1	To renew damaged parts, straighten and repair front chassis member, front fender, front door and aligned all parts.	\$ 1,600.00	\$ 1,400.00
2	To check wiring functions & conduct water leakage test.	\$ 180.00	\$ 150.00
3	To putty, apply primer & spray-paint the affected areas.	\$ 1,400.00	\$ 1,200.00
4	To apply rust-proofing on repaired/replaced panels.	\$ 180.00	\$ 150.00
	Total	\$ 6,170.00	\$ 5,710.00
The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :		\$ 4,550.00	


Fong Kok Heng
Qualified Appraiser











AUTOMAX SURV

4

AUTOMAX

















