

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT AXA INSURANCE PTE LTD Ref: CS3/ASM22000998/Evy3e2 8 SHENTON WAY #24-01 AXA TOWER Date: 11/02/2022 SINGAPORE 068811 ATTN: ONG KIAN THENG DERICK Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. SBG 1188A **SHD 166P** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. S2M03RZT Excess (\$) 0.00 ONG KIAN THENG DERICK **Assign Date** 27/01/2022 Assign From **Vehicle Particulars & Condition** 2. HONDA SHUTTLE 1496 Make & Model c.c HIDDEN 2018 Engine No. Year of Reg. GP71120538 SILVER Chassis No. Colour 107554 KM Odometer Steering **IN ORDER IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/60 R15 **GOODYEAR** 4 mm 185/60 R15 L/H Front Tyre **GOODYEAR** 4 mm 185/60 R15 GOODYEAR R/H Rear Tyre 4 mm GOODYEAR 4 mm L/H Rear Tyre 185/60 R15 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. 5. **General Information** 25/01/2022 07/02/2022 ( 11:00 AM ) Inspect Date / Time Accident Date MK VEHICLE ENTERPRISE Survey held at 48 TOH GUAN ROAD EAST #04-124 SINGAPORE 608586 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000-\$2,000

Report Ref No. CS3/ASM22000998/Evy3e2

**Estimate Days of Repair** 

Inspected By

**ESTIMATED NORMAL PERIOD FOR REPAIR:** 

5b.

**CHEN TSUE YEE** 

**Automotive Assessor** 

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

**REGD Auto Consultant-SAE, Licensed Appraiser** 

3 Working Days