

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG22001003/APA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000102
Claimant Vehicle No :	SKU8690P	Insured Vehicle No :	SMT7275T
Date of Loss:	26/01/2022	Nature of Claim:	TP
		Claim No:	1771887384SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU8690P	Engine No:	P520307830
Make & Model:	MAZDA 3, 1.5 SEDAN (A)	Chassis No:	JM6BM44A8G0316360
Reg. Date:	20/08/2015 (Man. Year: 2015)	Odometer:	96879 km
Colour:	Blue		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,807.20	5,482.40	3,324.80	37.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	880.00	670.00	43.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,357.20	6,362.40	3,994.80	38.57
Approved Total (Overridden) (S\$)		5,100.00		
Nett Amount (S\$)	10,357.20	5,100.00	5,257.20	50.76
+ Loss of Use (4.0 x S\$60.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,347.45		

INSPECTION

Date of Assignment:	26/01/2022	
Date Inspected:	26/01/2022	Inspected At: Ysk Auto Workshop (HQ) No.1 Kaki Bukit Avenue 6, #01-49 Autobay Singapore 417883
Estimated Period of Repair:	3.0 days	

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE	Missing	30.00 FS	*30.00 FS
2	1		*FRONT NUMBER PLATE HOLDER	Damaged	30.00 FS	*30.00 FS
3	1		*FRONT BUMPER	Distorted	1,031.70 F	*1,031.70 FL
4	1		*FRONT BUMPER SIDE HOLDER	O/S Damaged	49.80 F	*24.90 FL
5	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
6	1		*FRONT BUMPER REINFORCEMENT	Dented	464.40 F	*464.40 FL
7	1		*FRONT BUMPER TOP COVER	Deformed	285.80 F	*285.80 FL
8	1		*FRONT BUMPER NOZZLE PUMP RH	Cracked	189.40 F	*189.40 FL
9	1		*FRONT BUMPER NOZZLE PUMP COVER RH	Missing	35.20 F	*35.20 FL
10	1		*FRONT BUMPER FOG LAMP RH	Not Necessary	351.30 F	*- FL
11	1		*FRONT BUMPER FOG LAMP COVER RH	Cut	87.00 F	*87.00 FL
12	1		*FRONT BUMPER FOG LAMP BRACKET RH	Cracked	69.40 F	*69.40 FL
13	1		*FRONT BUMPER SIGNAL LAMP RH	Cracked	312.00 F	*312.00 FL
14	1		*FRONT BUMPER LOWER SPOILER	Deformed	1,200.00 FS	*900.00 FS
15	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	124.20 F	*- FL
16	1		*HEADLAMP RH	Cut	2,254.00 F	*2,254.00 FL
17	1		*FRONT GIRLLE	Cracked	589.00 F	*589.00 FL
18	1		*FRONT GIRLLE MOULDING RH	Cracked	176.70 F	*176.70 FL
19	1		*FRONT GRILLE LOGO	Necessary	71.00 F	*71.00 FL
20	1		*FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
21	1		*BONNET	Not Necessary	1,067.00 F	*- FL
22	1		*FRONT RH FENDER	Not Necessary	339.30 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,807.20	6,600.50
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	1,118.10
Total Parts (\$\$)	8,807.20	5,482.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	800.00	500.00
2	SPRAY PAINTING	New	700.00	350.00
3	WIRING	New	50.00	30.00
Gross Labour Cost (\$)			1,550.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >