

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001009/UQY3N2**Date:** 22/03/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00052392109

**Claimant Vehicle
No :** GBC4986P**Insured Vehicle
No :** GBA2664S

Date of Loss: 26/01/2022

Nature of Claim: TP

Claim
No: SNM22D200705/C02/TANKL**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **GBC4986P**

Make & Model: TOYOTA HIACE, 3.0 D MANUAL (M)

Engine No: 1KD2177939

Reg. Date: 28/09/2012 (Man. Year: 2012)

Chassis No: JTFHT02PX00090866

Colour: Silver

Odometer: 195805 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,078.05	4,184.18	1,893.87	31.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,625.00	2,450.00	1,175.00	32.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	9,703.05	6,634.18	3,068.87	31.63
Approved Total (Overridden) (\$\$)		5,300.00		
(\$\$)	9,703.05	5,300.00	4,403.05	45.38
+ GST 7.00/7.00% (\$\$)	679.21	371.00	308.21	45.38
Nett Amount (\$\$)	10,382.26	5,671.00	4,711.26	45.38

INSPECTION

Date of Assignment: 28/01/2022

Date Inspected: 08/03/2022 Inspected At:

Specialists Motor Pte Ltd (HQ)

Blk 3018A Ubi Road 1, #01-24/25/26

Singapore 408711

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 21 Mar 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D MANUAL (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC4986P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Badly Dented	1,712.42 FL	*1,712.42 FL
2	1		*REAR BOOT COVER LOGO	Necessary	66.80 FL	*66.80 FL
3	1		*REAR BOOT COVER LOCK	Dented / Jammed	371.45 FL	*371.45 FL
4	1		*REAR BOOT COVER LATCH	Not Necessary	165.90 FL	*- FL
5	1		*REAR BOOT COVER STICKER (TOYOTA)	Necessary	121.10 FL	*121.10 FL
6	1		*REAR BOOT COVER STICKER (HIACE)	Necessary	131.10 FL	*131.10 FL
7	2		*REAR NUMBER PLATE LAMP	Not Necessary	242.20 FL	*- FL
8	1		*REAR NUMBER PLATE LAMP GARNISH WITH HANDLE	Grazed	119.20 FL	*119.20 FL
9	1		*TAIL LAMP LH	Broken	256.90 FL	*256.90 FL
10	1		*REAR BUMPER FASCIA	Distorted	373.20 FL	*373.20 FL
11	1		*SET REAR BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
12	2		*REAR BUMPER SIDE RETAINER L&RH	Not Necessary	142.90 FL	*- FL
13	1		*REAR CORNER PANEL LH	Dented	170.10 FL	*170.10 FL
14	1		*REAR END PANEL	Badly Dented	374.45 FL	*374.45 FL
15	1		*FRONT BUMPER FASCIA	Deformed	425.10 FL	*425.10 FL
16	1		*SET FRONT BUMPER CLIPS	Necessary	48.00 FL	*48.00 FL
17	2		*FRONT BUMPER SIDE RETAINER L&RH	Not Necessary	387.60 FL	*- FL
18	1		*FRONT BUMPER TOWING COVER	Serviceable	24.60 FL	*- FL
19	1		*FRONT GRILLE	Cracked	974.42 FL	*974.42 FL
20	1		*FRONT WINDSCREEN GLASS WITH MOULDING	Not Necessary	1,191.30 FL	*- FL
21	1		*REAR BOOT COVER STICKER (70KM/H)	Necessary	28.00 FS	*10.00 FS
22	1		*SET REAR BUMPER PARKING SENSOR	Shorted	380.00 FS	*200.00 FS
23	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*20.00 FS
24	1		*REAR NUMBER PLATE	Bent	50.00 FS	*20.00 FS
25	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,914.74	5,482.24
- List Item Discount on L Items 25.00/25.00% (\$)	1,836.69	1,298.06
Total Parts (\$)	6,078.05	4,184.18

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OUT,RENEW,KNOCKING & WELDING HEADLAMP PANEL,REMOVE & INSTALL FRONT DAMAGE PARTS & RE-ALIGN BODY	New	780.00	300.00
2	CUT OUT,RENEW,KNOCKING & WELDING REAR BOOT COVER,REAR END PANEL,REAR SIDE PANEL LH,REMOVE & INSTALL ALL DAMAGE PARTS,STRAIGHTEN REAR CHASSIS & RE-ALIGN BODY	New	1,280.00	900.00
3	REMOVE & INSTALL REAR WINDSCREEN GLASS	New	120.00	120.00
4	REMOVE & INSTALL REAR BUMPER SENSOR	New	80.00	50.00
5	TUFF-KOTE ON DAMAGE PARTS	New	80.00	60.00
6	SPRAY PAINTING ON DAMAGE PARTS	New	1,250.00	1,000.00
7	CHECK ALL LIGHTING AFTER REPAIRS	New	35.00	20.00
Gross Labour Cost (\$\$)			3,625.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >