

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001011/UQY3Q2**Date:** 01/04/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNW00054452106

**Claimant Vehicle
No :** FBL2161T**Insured Vehicle
No :** GBA3587A

Date of Loss: 08/12/2021

Nature of Claim: TP

Claim
No: SNM21D207154/C02/TAYHPDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **FBL2161T**

Make & Model: ADIVA AR3 200, 171cc 3-WHEELER

Engine No: MA812089

Reg. Date: 15/07/2016 (Man. Year: 2016)

Chassis No: RGVTC40AAGA000065

Colour: Blue

Odometer: 0 km

Engine Capacity: 171 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70 R14

Rear Tyre Size: 120/70-12

Front Left Side: Shinko 6 mm

Rear Left Side: Shinko 6 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,583.00	4,914.80	7,668.20	60.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,872.00	1,345.00	1,527.00	53.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,455.00	6,259.80	9,195.20	59.50
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	15,455.00	5,000.00	10,455.00	67.65
+ GST 7.00/7.00% (S\$)	1,081.85	350.00	731.85	67.65
Nett Amount (S\$)	16,536.85	5,350.00	11,186.85	67.65

INSPECTION

Date of Assignment: 28/01/2022

Date Inspected: 09/02/2022

Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)

No. 6 Defu Lane 4

Singapore 539410

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2022)	
Parts:	N/A	ADIVA AR3 200 171cc 3-WHEELER (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBL2161T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ADAPTER MIRROR (AFTERMARKET)	Damaged	21.00 F	*21.00 FL
2	1		*AXLE HOLDER COMP LH	Bent	364.00 F	*364.00 FL
3	1		*SET BALL	Not Necessary	19.00 F	*- FL
4	1		*BALL SET SMALL	Not Necessary	14.00 F	*- FL
5	2		*BEARING 6005ZZ (NACHI)	Not Necessary	28.00 F	*- FL
6	4		*BEARING 6007-2RSR (FAG)	Necessary	100.00 F	*100.00 FL
7	2		*BEARING 6202-2NS (NACHI)	Necessary	28.00 F	*28.00 FL
8	1		*BEARING 6302-2NS (NACHI)	Necessary	14.00 F	*14.00 FL
9	8		*BEARING SUSPENSION LOWER 1	Not Necessary	104.00 F	*- FL
10	16		*BEARING SUSPENSION LOWER 2	Not Necessary	192.00 F	*- FL
11	1		*BOTTOM DUST GUARD	Not Necessary	27.00 F	*- FL
12	1		*BRACKET MUDGUARD REAR LH	Bent	82.00 F	*82.00 FL
13	1		*BRACKET UNDER FORK	Not Necessary	283.00 F	*- FL
14	1		*COVER SIDE LH	Cut	227.00 F	*227.00 FL
15	1		*FOOTBOARD LH	Broken	147.00 F	*147.00 FL
16	1		*FRAME REAR	Bent / Twisted	1,165.00 F	*1,165.00 FL
17	1		*GEAR BOX ASSY (V4)	Not Necessary	2,520.00 F	*- FL
18	1		*HEADLIGHT LH	Cracked	217.00 F	*217.00 FL
19	1		*HEADLIGHT RH (Scratched)	Not Consistent with The Impact	217.00 F	*- FL
20	1		*IGNITION STEERING LOCK SWITCH ASSY	Damaged	462.00 F	*462.00 FL
21	4		*LOCK CAM 30MM	Not Necessary	104.00 F	*- FL
22	1		*MIRROR (AFTERMARKET) LH	Cut	84.00 F	*84.00 FL
23	1		*MUDGUARD FRONT ASSY (UNPAINT)	Repair	112.00 F	*- FL
24	1		*MUDGUARD REAR METALLIC LH	Broken	84.00 F	*84.00 FL
25	1		*RACE STRG TOP COND	Not Necessary	27.00 F	*- FL
26	1		*RADIATOR	Not Necessary	318.00 F	*- FL
27	1		*RADIATOR GRILLE	Torn	70.00 F	*70.00 FL
28	1		*RIM REAR ASSY	N/S Bent	672.00 F	*336.00 FL
29	1		*RIM SPORT FRONT	Repair	448.00 F	*- FL
30	1		*ROD REAR FRAME CONNECTOR	Not Necessary	280.00 F	*- FL
31	4		*RUBBER BOOT (HARD)	Not Necessary	140.00 F	*- FL
32	1		*SEAL DUST STEERING CONE	Not Necessary	7.00 F	*- FL
33	1		*SHELVES REAR	Bent / Twisted	1,055.00 F	*1,055.00 FL
34	1		*SHIELD ASSY FRONT METALLIC (UNPAINT)	Broken	528.00 F	*528.00 FL
35	4		*SPACER SUSPENSION ARM LH	Not Necessary	168.00 F	*- FL
36	8		*SPACER SUSPENSION ARM RH	Not Necessary	240.00 F	*- FL
37	2		*STICKER (SINGAPORE POST) SIDE BOX LH	Not Necessary	84.00 FS	*- FS
38	2		*STICKER (SINGAPORE POST) SIDE BOX LH	Not Necessary	84.00 FS	*- FS
39	1		*STICKER (SINGPOST) BOX REAR	Not Necessary	232.00 FS	*- FS
40	1		*SUPPORT MIRROR LH	Not Necessary	9.00 F	*- FL
41	1		*TOP CAP	Not Necessary	27.00 F	*- FL
42	1		*TOP CAP	Not Necessary	27.00 F	*- FL
43	1		*TRANSMISSION SHAFT LH	Serviceable	954.00 F	*- FL
44	1		*VALVE RIM (3 PCS)	Necessary (1 PCS ONLY)	39.00 F	*13.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*REPAIR ON CENTER SIDE BOXES LH (LOCAL REPAIR)	Scratched	84.00 FS	*50.00 FS
46	1		*REPAIR ON REAR BOX (LOCAL REPAIR)	Scratched	112.00 FS	*80.00 FS
47	1		*REPAIR ON REAR SIDE BOXES LH (LOCAL REPAIR)	Scratched	84.00 FS	*50.00 FS
48	1		*REPAIR SADDLE (LOCAL REPAIR)	Scratched	104.00 FS	*80.00 FS
49	1		*BRACKET SIDE MIRROR LH	Cut	35.00 F	*35.00 FL
50	1		*CONNECTOR REAR FRAME	Damaged	140.00 F	*140.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	12,583.00	5,432.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	517.20
Total Parts (\$)	12,583.00	4,914.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR ON BODY ALIGNMENT	New	490.00	350.00
2	SPRAY PAINT ON REAR BOX }	New	980.00	360.00
3	SPRAY PAINT ON CENTER SIDE BOXES LH }	New	112.00	0.00
4	SPRAY PAINT ON REAR SIDE BOXES LH }	New	112.00	0.00
5	TRANSPORT CHARGES (MOTORCYCLE)	New	98.00	35.00
6	LABOUR	New	1,080.00	600.00
Gross Labour Cost (\$\$)			2,872.00	1,345.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >