Motor Appraiser and Insurance Loss Adjustor Blk 361 Yung An Road #12-105 Singapore 610361 Mobile: +65 9232 0012 Email: iconappraiser@gmail.com UEN.: 202006885Z

INVOICE

To: DEENUSON VEERIN

Date

19 Nov 2021

c/o :

: Celebrity Auto

176 Sin Ming Drive #03-17

Invoice No.

: 2021-00094

Sin Ming Autocare Singapore 575721 Ref

20211119/00094/CA

	DESCRIPTION	AMOUNT
Service rendered	for appraisal / inspection report :	
Professional	inspection fees	SGD 600.00
	Total	SGD 600.00
Singapore dollar	: SIX HUNDRED ONLY.	
Registration no.	: SKC1111K	
-	: TOYOTA C-HR HYBRID 1.8G CVT	
Our reference	: 20211119/00094/CA	
All payments made po	ayee to:-	
" ICON MOTOR AP	PRAISER PTE LTD"	
Please note payment terms:	- 30 days from invoice date	120

for ICON MOTOR APPRAISER PTE LTD

IICOIN MOTOR APPRAISER PTE LTD

Motor Appraiser and Insurance Loss Adjustor Blk 361 Yung An Road #12-105 Singapore 610361 Mobile: +65 9232 0012 Email: iconappraiser@gmail.com UEN.: 202006885Z

INSPECTION REPORT

To

DEENUSON VEERIN

Our ref.

: 20211119/00094/CA

Date

: 19 Nov 2021

REFERENCE

Assign by

DEENUSON VEERIN

Assign on Inspection on 11 Nov 2021

Accident on

11 Nov 2021 : 09 Nov 2021

Workshop name

: Celebrity Auto

Inspection at

: 176 Sin Ming Drive #03-17

Sin Ming Autocare Singapore 575721

PARTICULARS OF DAMAGED VEHICLE

Registration no.

: SKC1111K

Odometer

108778 km

Make / Model

TOYOTA C-HR HYBRID 1.8G CVT

Chassis no. Engine no.

ZYX102010773

Regn. date

2017

2ZR8029461

Body colour

White

Engine cap.

1797 cc

PRE-ACCIDENT CONDITION OF VEHICLE (STATIC CHECK ONLY)

Steering

In order

Paintwork

Fair

Fair

Footbrake Handbrake In order In order Undercarriage Gen. condition Serviceable

TYRE CONDITION ON VEHICLE

		Make	Size	Tread depth	Type of road wheel
Front N/S	:	Yokohama	225/50R18	70%	Alloy
Front O/S	:	Yokohama	225/50R18	70%	Alloy
Rear N/S	:	Yokohama	225/50R18	70%	Alloy
Rear O/S	:	Yokohama	225/50R18	70%	Alloy

NOTE: Tread depth percentages represents the visually estimated remaining life of tyre treads.

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

20211119/00094/CA

Page 1 of 2

POINT OF IMPACT

The damages was found on the rear portion.



RECOMMENDATION

The estimated cost of repair submitted by the repairer Celebrity Auto as per schedule attached has been revised and scrutinised, and in our opinion, we consider it to be fair and reasonable. The repairer have agreed to undertake the repairs at our recommendation.

Our adjusted cost of repair is SGD 10,376.75 to carry out the repairs. Kindly refer to parts and labour portion for a detailed account of the cost estimates.

REMARKS

However, for your information, under normal circumstances, the repair normally would take approximately **8 (Eight)** working days to complete.

We have **NOT AUTHORISED** the repair to the damaged vehicle. The survey was conducted strictly on a "WITHOUT PREJUDICE" basis.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our final report, which includes material damages photographs.

Yours faithfully.
ICON Motor Appraiser Pte Ltd



Note. This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis

List it	List items						
S/N	Parts description	QTY	Condition	Repairer's Estimate	Our Recommendation		
1	Rear bumper	1	Damaged	\$ 1,615.00	\$ 1,615.00		
2	Rear bumper lower	1	Damaged	\$ 725.00	\$ 725.00		
3	Rear bumper tow cover	1	Missing	\$ 71.00	\$ 71.00		
4	Rear bumper reinforcement	1	Bent	\$ 621.00	\$ 621.00		
5	Rear bumper retainer	2	Cracked	\$ 176.00	\$ 176.00		
6	Rear bumper bracket	2	Bent	\$ 108.00	\$ 108.00		
7	Rear bumper reflector o/s	1	Damaged	\$ 152.00	\$ 152.00		
8	Rear bumper reflector cover o/s	1	Damaged	\$ 274.00	\$ 274.00		
9	Tailgate	1	Damaged	\$ 2,025.00	\$ 2,025.00		
10	Tailgate lock	1	Re-use		(see		
11	Tailgate inner trim	1	Re-use		(**)		
12	Tailgate outer garnish	1	Damaged	\$ 745.00	\$ 745.00		
13	Tailgate release antenna	1	Damaged	\$ 278.00	\$ 278.00		
14	Tailgate 'C-HR' emblem	1	Necessary	\$ 59.00	\$ 59.00		
15	Tailgate 'Hybrid' emblem	1	Necessary	\$ 92.00	\$ 92.00		
16	Tailgate 'TOYOTA' logo	1	Necessary	\$ 76.00	\$ 76.00		
17	Rear windscreen moulding	1	Necessary	\$ 128.00	\$ 128.00		
18	End panel	1	Buckled	\$ 788.00	\$ 788.00		
19	End panel top garnish	1	Damaged	\$ 296.00	\$ 296.00		
	Subtotal			\$ 8,229.00	\$ 8,229.00		
	Discount (less 25.00%			\$ -	\$ 2,057.25		
			Total	\$ 8,229.00	\$ 6,171.75		

No.	Parts description	QTY	Condition	Repairer's Estimate	Our Re	ecommendation
1	Rear bumper clips	10	Necessary	\$ 55.00	\$	50.00
2	Tailgate inner trim clips	8	Necessary	\$ 44.00	\$	40.00
3	Tailgate outer garnish clips	8	Necessary	\$ 44.00	\$	40.00
4	Rear windscreen sealant	1	Necessary	\$ 100.00	\$	90.00
5	End panel sealant	1	Necessary	\$ 100.00	\$	90.00
6	End panel top garnish clips	6	Necessary	\$ 40.00	\$	30.00
7	Rear licence plate & frame	1	Damaged	\$ 65.00	\$	55.00
8	Reverse sensor	2	Damaged	\$ 480.00	\$	480.00
9	Reverse camera	1	Malfunction	\$ 530.00	\$	530.00
10	Sundries	1	Necessary	\$ 60.00	\$	50.00
		\$ 1,518.00	\$	1,455.00		

Labo	ur					
No.	Description	QTY	Repairer's Estimate		Our Recommendation	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	1	\$	1,600.00	\$	1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	1	\$	60.00	\$	50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	1	\$	100.00	\$	80.00
4	To remove and refit rear windscreen to facilitate repair work.	1	\$	150.00	\$	140.00
5	Supply spray paint material and necessary items to respray affected area / panel.	1	\$	1,200.00	\$	1,000.00
6	To rust proof all affected portions after repair.	1	\$	100.00	\$	80.00
		\$	3,210.00	\$	2,750.00	

Estimate Grand Total \$ 12,957.00 \$ 10,376.75

Our Ref:

20211119/00094/CA

Your Ref:















Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20211119/00094/CA


Your Ref:















Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20211119/00094/CA

Your Ref:





Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.


Our Ref:


20211119/00094/CA

Your Ref:















Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:


20211119/00094/CA

Your Ref:














Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20211119/00094/CA

Your Ref:



Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

UGOIN MOTOR APPRAISER PTE LTD

Our Ref:

20211119/00094/CA

Your Ref:




Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20211119/00094/CA

Your Ref:



Our Ref:

20211119/00094/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

Our Ref:

20211119/00094/CA

Your Ref:













Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.