

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22001024/VQY3N2**Date:** 24/02/2022**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MM000071		
Claimant Vehicle No :	SHC2277U	Insured Vehicle No :	SLK5877D		
Date of Loss:	27/01/2022	Nature of Claim:	TP	Claim No:	M2200545

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2277U	Engine No:	G4LEKU432098
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU195109
Reg. Date:	28/09/2021 (Man. Year: 2019)	Odometer:	14748 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,645.72	613.60	1,032.12	62.72
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,080.00	660.00	420.00	38.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,736.72	1,284.60	1,452.12	53.06
+ GST 7.00/7.00% (S\$)	191.57	89.92	101.65	53.06
Nett Amount (S\$)	2,928.29	1,374.52	1,553.77	53.06

INSPECTION

Date of Assignment:	31/01/2022	
Date Inspected:	28/01/2022	Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Feb 2022)
Parts:	143	HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC2277U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
2	1		*REAR BUMPER MOULDING	Cut	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT	Serviceable	394.80 FL	-	*- FL
4	2		*REAR BUMPER REINFORCEMENT STAY LH /RH	Serviceable	276.20 FL	-	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REAR BUMPER REFLECTOR RH	Serviceable	41.45 FL	-	*- FL
7	1		*REAR BUMPER BRACKET RH	Serviceable	55.80 FL	-	*- FL
8	1		*REAR BUMPER MAT	Serviceable	50.00 FS	-	*- FS
9	1		*REAR REVERSE SENSOR	Cut	180.00 FS	-	*180.00 FS
10	1		*REAR NUMBER PLATE W/HOLDER	Cracked	55.00 FS	-	*55.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	1,985.90	708.25
					- List Item Discount on L Items 20.00/20.00% (\$\$)	340.18	94.65
					Total Parts (\$\$)	1,645.72	613.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	20.00
4	TUFF KOTE	New	60.00	20.00
5	CHECK WIRING LIGHTING	New	60.00	20.00
Gross Labour Cost (\$\$)			1,080.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >