

Our Job Ref No : 305503012

Date : 31/01/22

ENGINEERING

ComfortDaiGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Attn : THEVAN

Vehicle Reg No. : SHC2277U

Fax :

27/01/2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2. The repair job shall bill to: TOKIO MARINE SLK5877D

2. The finalized amount shall be

(a) Spare Parts after List discount \$613.60

(b) Labour Charges \$660.00

Total for Part-By-Part Repair Cost \$1,273.60

(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
Final Lumpsum Repair cost \_\_\_\_\_

3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : \_\_\_\_\_

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : \_\_\_\_\_

Name : Thevan

Date : \_\_\_\_\_

For Official Use Only

| Item                                                 | Amount        | Document Attached Yes or No | Confirm By (Signature) | Remarks |
|------------------------------------------------------|---------------|-----------------------------|------------------------|---------|
| 1. Rental Rate P/Day                                 |               | YES                         |                        |         |
| 2. Loss of Income Paid                               | -             | N                           |                        |         |
| 3. Survey Fees                                       | -             | -                           |                        |         |
| 4. LTA Search Fee                                    | \$7.49/\$2.00 |                             |                        |         |
| 5. Medical Fees (on behalf of driver, if applicable) |               |                             |                        |         |
| 6. Overrun                                           |               |                             |                        |         |

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

**REPAIR DETAILS****Reference**

**Part Source:** MRM-SG      **Version:** 1.0 (Last Synchronised: 27 Jan 2022)

**Parts:** 143      **HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**

**Labour:** Repairer's      **(Price-denominated Standard List)**

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

| No. | Qty | Part No. | Particulars                            | %Disc | %Depr | Amount              |
|-----|-----|----------|----------------------------------------|-------|-------|---------------------|
| 1   | 1   |          | *REAR BUMPER                           | 20.00 | 0.00  | *459.40 FL Xr       |
| 2   | 1   |          | *REAR BUMPER MOULDING                  | 20.00 | 0.00  | *451.25 FL Sdkt     |
| 3   | 1   |          | *REAR BUMPER REINFORCEMENT             | 20.00 | 0.00  | *394.80 FL 1, X Svc |
| 4   | 2   |          | *REAR BUMPER REINFORCEMENT STAY LH /RH | 20.00 | 0.00  | *276.20 FL 1, X Svc |
| 5   | 10  |          | *REAR BUMPER CLIPS                     | 20.00 | 0.00  | *22.00 FL / nec     |
| 6   | 1   |          | *REAR BUMPER REFLECTOR RH              | 20.00 | 0.00  | *41.45 FL X Svc     |
| 7   | 1   |          | *REAR BUMPER BRACKET RH                | 20.00 | 0.00  | *55.80 FL X Svc     |
| 8   | 1   |          | *REAR BUMPER MAT                       | 0     | 0.00  | *50.00 FS X Svc     |
| 9   | 1   |          | *REAR REVERSE SENSOR                   | 0     | 0.00  | *180.00 FS / cut    |
| 10  | 1   |          | *REAR NUMBER PLATE W/HOLDER            | 0     | 0.00  | *55.00 FS / crn     |

F=Franchise part, S=SpcNett, L=ListItemDisc.

|                                              |                 |
|----------------------------------------------|-----------------|
| <b>Sub Total (S\$)</b>                       | <b>1,985.90</b> |
| <b>- List Item Discount on L Items (S\$)</b> | <b>340.18</b>   |
| <b>Total Parts (S\$)</b>                     | <b>1,645.72</b> |

ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

378.6

613.6

22. 5:04 PM

Repairer Estimates

# Estimates on Miscellaneous Items

No Qty Particulars

## Miscellaneous Items

1 1 OD/TP Case (Insurer)

Amount

11.00

Sub Total (S\$)

11.00

# Estimates on Labour

No Particulars

## Labour Items

1 PANEL BEATING

2 SPRAY PAINTING

3 REMOVE/REFIX REVERSE SENSOR

4 TUFF KOTE

5 CHECK WIRING LIGHTING

Lab.Type

Amount

New

600.00 350

New

300.00 250

New

60.00 20

New

60.00 26

New

60.00 20

Gross Labour Cost (S\$)

1,080.00

ComfortDelGro Engineering Pte Ltd/SHC2277U/27/01/2022 17:01. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Therav@Lkhauto.com

82235769

28/1/22 1630

P/P for paint photo

2 days up

LKK Auto Insurance hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: