



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLZ 8422J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	CUT	2,150.00	1,421.00
1	FRONT BUMPER SIDE RETAINER LH	NECESSARY	98.60	38.00
1	FRONT BUMPER REINFORCEMENT	NOT DAMAGED	650.00	-
2	FRONT BUMPER PARKING SENSOR @\$310.45	N/S SHORT CIRCUIT	620.90	100.00
1	FRONT BUMPER FOG LAMP GARNISH LH	BROKEN	180.00	78.00
1	FRONT BUMPER OUTER GARNISH LH	BROKEN	385.60	385.60
1	FRONT BUMPER LOWER SIDE LIP LH	NOT DAMAGED	210.00	-
1	FRONT SUPPORT PANEL	NOT DAMAGED	952.89	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT DAMAGED	345.20	-
1	FRONT FENDER LH	BENT	1,011.00	980.00
1	FRONT FENDER INNER COWLING LH	NOT DAMAGED	415.30	-
1	HEADLAMP LH	BROKEN	2,610.20	2,579.00
1	HEADLAMP LOWER BRACKET LH	NO SUCH PARTS	375.60	-
1	HEADLAMP PANEL LH	NOT DAMAGED	510.50	-
1	FRONT KNUCKLE ARM LH	DENTED	785.30	785.30
1	FRONT KNUCKLE ARM BEARING LH	JAMMED	285.60	285.60
	LESS 10% DISCOUNT		-1,158.67	-665.25
			10,428.02	5,987.25
<u>SPECIAL NETT ITEMS</u>				
1	SUNDRIES (SN)	NOT NECESSARY	80.00	-
1	FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	FRONT BUMPER FOG LAMP GARNISH CLIPS (SN)	NO SUCH PARTS	60.00	-
1	FRONT BUMPER OUTER GARNISH CLIPS (SN)	NO SUCH PARTS	60.00	-
4	FRONT BUMPER PARKING SENSOR SEAL @\$58.00 (SN)	NECESSARY	232.00	140.00
1	FRONT BUMPER LOWER SIDE LIP CLIPS (SN)	NO SUCH PARTS	60.00	-
1	FRONT SUPPORT PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	FRONT FENDER SEALANT (SN)	NECESSARY	100.00	30.00
1	FRONT FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	FRONT TYRE (SN)	NOT DAMAGED	480.00	-
1	FRONT ALLOY RIM (SN)	CUT	1,850.00	1,250.00

Report Ref No. CS/SMR22001046/Bty3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	NOT DAMAGED	80.00	-
			3,222.00	1,450.00
	LABOUR			
	R & R FRONT BUMPER PARKING SENSOR.		100.00	60.00
	R & R FRONT UNDER CARRIAGE.		150.00	80.00
	R & R FRONT TYRE AND BALANCING.		100.00	30.00
	WHEEL ALIGNMENT.		180.00	60.00
	DIAGNOSTIC RESET FAULT CODE.		300.00	120.00
	CHECK WIRING.		150.00	30.00
	UPHOLSTERY.	NOT NECESSARY	300.00	-
	PANEL BEATING.		1,400.00	1,000.00
	RUST PROOFING.	NOT NECESSARY	200.00	-
	SPRAY PAINTING.		1,400.00	400.00
			4,280.00	1,780.00
GRAND TOTAL			17,930.02	9,217.25

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,350.00
---	--	--	-----------------

Report Ref No. CS/SMR22001046/Bty3n2

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.