

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22001050/RVY3E2

**Date:** 09/05/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00155002100  
**Claimant Vehicle No :** SDZ8091A **Insured Vehicle No :** XE7035T  
Date of Loss: 26/01/2022 Nature of Claim: TP Claim No: SNM22D200716/C02/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDZ8091A**  
Make & Model: VOLKSWAGEN GOLF, 1.2 TSI (A) Engine No: CYV377692  
Reg. Date: 16/03/2016 (Man. Year: 2015) Chassis No: WVVZZZAUZGW146461  
Colour: White Odometer: 107548 km  
Engine Capacity: 1197 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm  
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,365.95	7,276.33	2,089.62	22.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,640.00	10,080.00	5,560.00	35.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>25,005.95</b>	<b>17,356.33</b>	<b>7,649.62</b>	<b>30.59</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,750.42</b>	<b>1,214.94</b>	<b>535.48</b>	<b>30.59</b>
<b>Nett Amount (S\$)</b>	<b>26,756.37</b>	<b>18,571.27</b>	<b>8,185.10</b>	<b>30.59</b>

### INSPECTION

Date of Assignment: 10/02/2022  
Date Inspected: 09/02/2022 Inspected At: Volkswagen Centre Singapore (HQ)  
247 Alexandra Road  
Singapore 159934  
Estimated Period of Repair: 9.0 days

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$440.54 NETT)

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2022)
<b>Parts:</b>	144	VOLKSWAGEN GOLF 1.2 TSI (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDZ8091A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR VIEW MIRROR HOUSING	Not Necessary	631.57 FS	*- FS
2	1		*MIRROR CAP PRIMED	Repair	181.52 FS	*- FS
3	1		*MIRROR GLASS	Not Necessary	205.00 FS	*- FS
4	1		*DOOR RHS FRT DOOR	Torn	1,987.16 FS	*1,987.16 FS
5	1		*DOOR SEAL	Necessary	114.38 FS	*114.38 FS
6	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	43.65 FS	*43.65 FS
7	2		*BOLT WITH POLYGON SOCKET	Necessary	11.08 FS	*11.08 FS
8	2		*FILL.HD.SCREW	* Check	6.06 FS	*- FS
9	1		*BOW SUPPORT DOOR HANDLE	* Check	137.27 FS	*- FS
10	6		*CLIP	* Check	10.20 FS	*- FS
11	1		*DOOR RHS REAR DOOR	Torn	2,319.74 FS	*2,319.74 FS
12	1		*DOOR SEAL OUTER	Necessary	114.38 FS	*114.38 FS
13	1		*SOUND ABSORBER LAMINATED DOOR INSULATOR	Necessary	43.65 FS	*43.65 FS
14	2		*BOLT WITH POLYGON SOCKET	Necessary	11.08 FS	*11.08 FS
15	2		*FILL.HD.SCREW	* Check	6.06 FS	*- FS
16	6		*CLIP	* Check	10.20 FS	*- FS
17	1		*DOOR LATCH RHS REAR DOOR LOCK	Not Necessary	463.67 FS	*- FS
18	1		*GLASS CHANNEL BLACK	* Check	270.75 FS	*- FS
19	1		*SECTIONAL PARTS SIDE PANEL RHS REAR FENDER	Bent	1,860.22 FS	*1,860.22 FS
20	1		*2K-FULLSCHAUM	Necessary	162.95 FS	*162.95 FS
21	1		*SEALANT CAN BE SPRAYED	Necessary	66.64 FS	*66.64 FS
22	1		*2K-BODY ADHESIVE	Necessary	468.68 FS	*468.68 FS
23	1		*GUIDE PIECE LHR BUMPER BRACKET (SIDE)	Not Necessary	41.83 FS	*- FS
24	1		*GUIDE PIECE RHR BUMPER BRACKET (SIDE)	Not Necessary	41.83 FS	*- FS
25	1		*GUIDE PIECE LHR BUMPER BRACKET (UPPER)	Not Necessary	41.83 FS	*- FS
26	1		*GUIDE PIECE RHR BUMPER BRACKET (UPPER)	Not Necessary	41.83 FS	*- FS
27	1		*ZINC SPRAY	Necessary	72.72 FS	*72.72 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **9,365.95**      **7,276.33**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	280.00
2	B&P DIAGNOSIS AND PROGRAMMING	New	480.00	480.00
3	LABOUR	New	6,720.00	5,040.00
4	SPRAY PAINT	New	4,800.00	2,600.00
5	TRANSFER DOOR MECHANISM	New	1,680.00	840.00
6	R&R REAR SEAT	New	840.00	420.00
7	R&R REAR LUGGAGE TRIM	New	840.00	420.00
<b>Gross Labour Cost (\$\$)</b>			<b>15,640.00</b>	<b>10,080.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >