

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001053/ETY3Q2**Date:** 14/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00049822100	
Claimant Vehicle No :	SML663U	Insured Vehicle No :	SLA9878C	
Date of Loss:	28/01/2022	Nature of Claim:	TP	Claim No: SNM22D200751/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML663U		
Make & Model:	BENTLEY FLYING SPUR V8, 4.0 ABS 4WD S/R (A)	Engine No:	CYC020864
Reg. Date:	05/04/2019 (Man. Year: 2018)	Chassis No:	SCBEE53W6JC070240
Colour:	Blue	Odometer:	56397 km
Engine Capacity:	3993 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35Z R21	Rear Tyre Size:	275/35Z R21
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	70,023.99	57,227.07	12,796.92	18.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	19,765.00	12,065.00	7,700.00	38.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	89,788.99	69,292.07	20,496.92	22.83
+ GST 7.00/7.00% (S\$)	6,285.23	4,850.44	1,434.79	22.83
Nett Amount (S\$)	96,074.22	74,142.51	21,931.71	22.83

INSPECTION

Date of Assignment:	04/02/2022	
Date Inspected:	04/02/2022	Inspected At: 2 JALAN PESAWAT
Estimated Period of Repair:	5.0 days	Repairer: Wearnes Automotive Pte Ltd (Leng Kee)

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 BENTLEY FLYING SPUR V8 4.0 ABS 4WD S/R (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SML663U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER	Cut	120.00 FS	*120.00 FS
2	1		*BUMPER COVER UNPRIME	Dented	16,208.00 FS	*14,587.20 FS
3	1		*REAR SPOILER	Cut	5,987.60 FS	*5,388.84 FS
4	1		*REAR SPOILER PRIMED	Missing	4,421.60 FS	*3,979.44 FS
5	1		*GUIDE PROFILE LH	Not Necessary	461.70 FS	*- FS
6	1		*GUIDE PROFILE RH	Not Necessary	461.70 FS	*- FS
7	1		*GUIDE PROFILE CTR	Not Necessary	757.40 FS	*- FS
8	1		*BUMPER CARRIER	Not Necessary	2,457.30 FS	*- FS
9	1		*MOUNTING FOR BUMPER	Not Necessary	270.30 FS	*- FS
10	1		*MOUNTING FOR BUMPER	Not Necessary	270.30 FS	*- FS
11	1		*COVER FOR TOWING EYE	Crushed	389.40 FS	*350.46 FS
12	1		*TRIM FOR BUMPER	Cut	1,620.80 FS	*1,458.72 FS
13	1		*COVER TRIM	Broken	2,993.80 FS	*2,694.42 FS
14	1		*SEALING TAPE	Not Necessary	178.50 FS	*- FS
15	1		*REAR LID	Broken	22,286.20 FS	*20,057.58 FS
16	1		*BADGE	Necessary	220.30 FS	*198.27 FS
17	1		*SWITCH	Not Necessary	1,071.50 FS	*- FS
18	1		*TRIM FOR EXHAUST TAI	Cut	2,349.20 FS	*2,114.28 FS
19	1		*TRIM FOR EXHAUST TAI	Cut	2,349.20 FS	*2,114.28 FS
20	2		*BRACKET FOR DISTANCE	Not Necessary	99.60 FS	*- FS
21	2		*BRACKET FOR DISTANCE	Not Necessary	84.60 FS	*- FS
22	4		*SEAL SENSOR PDC	Not Necessary	18.00 FS	*- FS
23	1		*ADHESIVE SEALER FL2	Not Necessary	775.00 FS	*- FS
24	1		*3M07333 IMPACT RESIS	Necessary	84.10 FS	*75.69 FS
25	1		*LED FOG RR LAMP REVE	Broken	2,972.70 FS	*2,972.70 FS
26	1		*UNDERBODY TRIM	Missing	1,088.19 FS	*1,088.19 FS
27	12		*SCREW ST5 X 16LG FLN	Necessary	27.00 FS	*27.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **70,023.99** **57,227.07**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER ,TAILGATE ,LOWER COVER ,EXHAUST ,ETC	New	9,600.00	3,200.00
2	TO SPRAYPAINT & BLEND ON REAR BUMPER ,TAILGATE ,FENDER REAR	New	6,500.00	5,200.00
3	TO REMOVE ,REFIT & TRANSFER REAR BOOT COMPONENTS	New	1,600.00	1,600.00
4	TO CHECK WIRING INCLUDE RESETTNG OF ALL ELECTRICAL MODULES	New	2,065.00	2,065.00
Gross Labour Cost (\$\$)			19,765.00	12,065.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >