



Your Ref : 4192902740SG

Date: 03<sup>th</sup> Mar 2022

Our Ref : CS4/AIG22001055/Nqy3e2

**M/s AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBF 9147X  
ACCIDENT ON 27/01/2022**

Instruction was received to inspect the vehicle Reg. No. GBF 9147X. The inspection was conducted on 04/02/2022 at the premises of M/s Kan Fook Sing Motor Workshop, 61 Defu Lane 12, Singapore 539147.

The following vehicle information was recorded:

Registration Number	: GBF 9147X
Make/Model	: Toyota Proace 1.6 Manual
Year of Registration	: 2017
Body Colour	: Silver
Chassis Number	: YARVBBHVVBGZ056872
Engine Capacity	: 1560 cc

The vehicle caught fire. The cause of fire probably due to short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 45,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 24,025.00)
Nett Liability	<u>S\$ 20,975.00</u> =====

Vehicle Inspected By:



MUHD NAZRIL (NAZ)  
Technical Investigator  
LL.B. (Hons) London



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust),MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE,MIMI,MSAE,MCIARD, AM,NIJAAR(USA),  
AM CATARI(CAN),M.MATA(USA),M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.