



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 291E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT DOOR RH	DENTED	1,306.36	1,154.00
1	FRONT DOOR FRAME BLACK STICKER LONG RH	NECESSARY	118.10	95.00
1	FRONT DOOR FRAME BLACK STICKER VERTICAL RH	NECESSARY	78.20	48.00
1	FRONT DOOR SIDE MIRROR ASSY RH	BROKEN	658.10	645.00
1	FRONT DOOR SIDE MIRROR COVER RH	BROKEN	66.90	66.90
1	FRONT DOOR QUARTER GARNISH RH	CUT	83.70	83.70
1	FRONT DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	126.00	-
1	FRONT DOOR WEATHERSTRIP RH	NOT DAMAGED	129.00	-
	LESS 25% DISCOUNT		-	-523.15
			2,566.36	1,569.45
<u>SPECIAL NETT ITEMS</u>				
1	TWEETER (SN)	NOT DAMAGED	150.00	-
			150.00	-
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEATING FRONT RH DOOR PILLAR AND FRONT RH FRAME MEMBERS.TO REMOVE,TRANSFER AND REFIT FRONT RH DOOR COMPONENTS.		600.00	300.00
	TO PUTTY,RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		700.00	300.00
	TO CHECK AND RECTIFY WIRING SYSTEM.	NOT NECESSARY	80.00	-
	TO RUST PROOF AFFECTED AREAS.		90.00	30.00
			1,470.00	630.00
GRAND TOTAL			4,186.36	2,199.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,750.00

Report Ref No. CS3/CT121005629/Bvy3n2-1

LIM TEOW GUAN

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.