

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD CS3/LPC21002885/R1tf3e2 Ref: 300 BEACH ROAD Date: 19/03/2021 #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. YP 972P **GBB 6683E** Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 20/21/21/VC05/024289 Excess (\$) 0.00 ONG LI LI **Assign Date** 02/03/2021 Assign From 2. **Vehicle Particulars & Condition** MITSUBISHI CANTER Make & Model 2998 C.C FEB21ER Engine No. **HIDDEN** Year of Reg. 2016 Chassis No. FEB21EA10706 Colour WHITE 132676 KM **IN ORDER** Odometer Steering **IN ORDER** NIL **Brakes** Modification **FAIR** General **Conditions of Tyres** 3. Size Make **Balance** 195/85 R15 YOKOHAMA 7 mm R/H Front Tyre 195/85 R15 YOKOHAMA L/H Front Tyre 7 mm R/H Rear Tyre 195/85 R15 (D) YOKOHAMA 7/7 mm 195/85 R15 (D) YOKOHAMA 7/7 mm L/H Rear Tyre 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information Accident Date** 01/03/2021 **Inspect Date / Time** 03/03/2021 (05:10 PM) NGEE NGEE MOTOR Survey held at BLK 1 NO: 22 PANDAN LOOP SINGAPORE 128219 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

Report Ref No. CS3/LPC21002885/R1tf3e2

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

Tu

K.K.LAU CPT(RET)

Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser